

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21009926/EQCE2

**Date:** 15/11/2021

### REFERENCE

Insured/Claimant: NG HOCK CHUAN Policy No: 2070151462  
Date of Loss: 20/09/2021 Nature of Claim: OD Claim No: 1389415566SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJW5117A**  
Make & Model: AUDI A4, 2.0 TFSI S-TRONIC (A) Engine No: DEM025292  
Reg. Date: 26/10/2020 (Man. Year: 2020) Chassis No: WAUZZZF4XMN000749  
Colour: Black Odometer: 14789 km  
Engine Capacity: 1984 cc  
Market Value/New Car Price: S\$149,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17  
Front Left Side: Hankook 4 mm Rear Left Side: Hankook 4 mm  
Front Right Side: Hankook 4 mm Rear Right Side: Hankook 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,214.00	5,927.04	5,286.96	47.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,392.00	3,402.00	7,990.00	70.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,606.00</b>	<b>9,329.04</b>	<b>13,276.96</b>	<b>58.73</b>
<b>- Excess (S\$)</b>	<b>1,100.00</b>	<b>1,100.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>21,506.00</b>	<b>8,229.04</b>	<b>13,276.96</b>	<b>61.74</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,505.42</b>	<b>576.03</b>	<b>929.39</b>	<b>61.74</b>
<b>Nett Amount (S\$)</b>	<b>23,011.42</b>	<b>8,805.07</b>	<b>14,206.35</b>	<b>61.74</b>

### INSPECTION

Date of Assignment: 23/09/2021  
Date Inspected: 23/09/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH	Dented	3,192.00 FS	*2,553.60 FS
2	8		*RIVETTED CAP NUT	Not Necessary	24.00 FS	*- FS
3	1		*FRONT DOOR OUTER SEAL - LH	Necessary	205.00 FS	*164.00 FS
4	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
5	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
6	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
7	1		*FRONT DOOR ATTACHMENT PARTS - LH	Not Necessary	1,050.00 FS	*- FS
8	1		*FRONT DOOR CATCH	Not Necessary	105.00 FS	*- FS
9	1		*FRONT DOOR HANDLE TRIM - LH	Missing	88.00 FS	*69.92 FS
10	1		*FRONT DOOR HOUSING - LH	Cut	8.00 FS	*5.92 FS
11	1		*FRONT HANDLE DOOR COVER - LH	Missing	6.00 FS	*4.64 FS
12	1		*FRONT DOOR HANDLE SENSOR - LH	Cut	228.00 FS	*182.40 FS
13	1		*FRONT DOOR EXTERIOR HANDLE - LH	Cut	44.00 FS	*34.88 FS
14	2		*FRONT DOOR HANDLE UNDERLAY RUBBER - LH FRONT / REAR	Necessary	8.00 FS	*5.76 FS
15	1		*FRONT DOOR MOUNTING BAR - LH	Not Necessary	164.00 FS	*- FS
16	1		*REAR DOOR - LH	Dented	3,192.00 FS	*2,553.60 FS
17	13		*RIVETTED CAP NUT	Not Necessary	39.00 FS	*- FS
18	1		*REAR DOOR OUTER SEAL - LH	Necessary	205.00 FS	*164.00 FS
19	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
20	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
21	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
22	1		*REAR DOOR SEALING STRIP - LH	Not Necessary	17.00 FS	*- FS
23	1		*REAR DOOR ATTACHMENT PARTS - LH	Not Necessary	860.00 FS	*- FS
24	1		*REAR DOOR CATCH	Not Necessary	120.00 FS	*- FS
25	1		*REAR DOOR UPPER HINGE - LH	Not Necessary	44.00 FS	*- FS
26	1		*REAR DOOR LOWER HINGE - LH	Not Necessary	46.00 FS	*- FS
27	1		*FRONT DOOR UPPER HINGE - LH	Not Necessary	45.00 FS	*- FS
28	1		*FRONT DOOR LOWER HINGE - LH	Not Necessary	46.00 FS	*- FS
29	1		*REAR INNER DOOR SEAL - LH	Not Necessary	222.00 FS	*- FS
30	1		*FRONT WINDOW REGULATOR WITHOUT MOTOR - LH	Not Necessary	282.00 FS	*- FS
31	1		*REAR DOOR SILL TRIM - LH	Not Necessary	120.00 FS	*- FS
32	1		*AIRBAG / CHILDS SEAT STICKER	Not Necessary	24.00 FS	*- FS
33	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
34	1		*SUNDRIES	Necessary	400.00 FS	*8.32 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 11,214.00 5,927.04**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	700.00	560.00
2	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS B-PILLAR AND LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
3	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, HINGES, LHS SILL PANEL, LHS B-PILLAR, DOOR HANDLE AND DOOR ENTRANCES	New	4,500.00	1,650.00
4	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER	New	800.00	0.00
5	TO PUT CAR ON THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	New	2,400.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			<b>Gross Labour Cost (\$\$)</b>	<b>11,392.00</b>
				<b>3,402.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >