

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009928/KTCN2**Date:** 05/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00085792104

Claimant Vehicle No : GBF9433U **Insured Vehicle No :** GBD9949J

Date of Loss: 20/09/2021 Nature of Claim: TP Claim No: SNM21D205390/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF9433U**

Make & Model: TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M) Engine No: 1KD2681179

Reg. Date: 20/04/2017 (Man. Year: 2016) Chassis No: KDY2318028002

Colour: White Odometer: 194632 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15X8 Rear Tyre Size: 155R12X8(D)

Front Left Side: Condor 7 mm Rear Left Side: Triangle 9/9 mm

Front Right Side: Condor 7 mm Rear Right Side: Triangle 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,915.50	1,154.14	8,761.36	88.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	840.00	1,910.00	69.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,665.50	1,994.14	10,671.36	84.26
Approved Total (Overridden) (\$\$)		1,500.00		
(\$\$)	12,665.50	1,500.00	11,165.50	88.16
+ GST 7.00/7.00% (\$\$)	886.59	105.00	781.59	88.16
Nett Amount (\$\$)	13,552.09	1,605.00	11,947.09	88.16

INSPECTION

Date of Assignment: 28/03/2022

Date Inspected: 10/01/2022 Inspected At: Thiam Heng Huat Pte Ltd (SIN MING)
176 SIN MING DRIVE, #05-14
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Apr 2022)	
Parts:	N/A	TOYOTA DYNA 3.0 D TURBO M/T 2WD (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF9433U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,997.00 FL	*1,498.85 FL
2	4		*TAIL GATE HINGE	Repair	272.00 FL	*- FL
3	2		*TAIL GATE STOPPER	Serviceable	126.00 FL	*- FL
4	2		*TAIL GATE STOPPER BRACKET	Repair	306.00 FL	*- FL
5	1		*TAIL GATE LOWER PANEL	Repair	958.00 FL	*- FL
6	2		*TAIL LAMP PANEL	Repair	766.00 FL	*- FL
7	2		*TAIL LAMP	Serviceable	746.00 FL	*- FL
8	2		*REAR LICENCE PLATE LAMP	Serviceable	154.00 FL	*- FL
9	1		*REAR FLOOR PANEL	Repair	1,487.00 FL	*- FL
10	1		*REAR LICENCE PLATE BASE PANEL	Repair	150.00 FL	*- FL
11	1		*REAR SPARE TYRE CARRIER	Repair	486.00 FL	*- FL
12	4		*TAIL GATE HINGE PIN	Serviceable	536.00 FL	*- FL
13	2		*TAIL GATE LOCK	Repair	552.00 FL	*- FL
14	1		*TAIL GATE LOWER MEMBER	Repair	1,714.00 FL	*- FL
15	2		*TAIL GATE LOWER MEMBER HOOK	Repair	316.00 FL	*- FL
16	1		*EXHAUST SILENCER	Repair	782.00 FL	*- FL
17	1		*EXHAUST HANGER	Serviceable	66.00 FL	*- FL
18	1		*REAR NUMBER PLATE	Serviceable	55.00 FS	*- FS
19	1		*TAIL GATE TOYOTA STICKER	Not Necessary	180.00 FS	*- FS
20	1		*TAIL GATE 70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
21	1		*TAIL GATE DYNA STICKER	Necessary	15.00 FS	*15.00 FS
22	2		*SPARE TYRE	Serviceable	760.00 FS	*- FS
23	1		*REVERSE SENSOR	Serviceable	280.00 FS	*- FS
24	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,769.00	1,528.85
- List Item Discount on L Items 25.00/25.00% (\$)	2,853.50	374.71
Total Parts (\$)	9,915.50	1,154.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,000.00	400.00
2	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	New	50.00	10.00
3	TO REMOVE AND REPLACE,STRAIGHTEN AND RE-ADJUST EXHAUST PIPE	New	100.00	0.00
4	TO ALIGN REAR CARGO FRAME AND TO CONDUCT CHASSIS ALIGNMENT ON CAR-O-LINER	New	400.00	0.00
5	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,000.00	400.00
6	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	200.00	30.00
Gross Labour Cost (\$\$)			2,750.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >