

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB21009929/UTF3N2**Date:** 23/11/2021REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SLC9633G **Insured Vehicle No :** SNB5695K
 Date of Loss: 23/09/2021 Nature of Claim: TP Claim No: MFL2021D0004175

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC9633G**
 Make & Model: KIA CARENS, 1.7 D SUNROOF (A) Engine No: D4FDGH106374
 Reg. Date: 31/05/2016 (Man. Year: 2016) Chassis No: KNAHU815VG7153802
 Colour: Blue Odometer: 115071 km
 Engine Capacity: 1685 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,495.40	5,265.30	230.10	4.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,330.00	2,620.00	2,710.00	50.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,825.40	7,885.30	2,940.10	27.16
Approved Total (Overridden) (S\$)		6,300.00		
(S\$)	10,825.40	6,300.00	4,525.40	41.80
+ GST 7.00/7.00% (S\$)	757.78	441.00	316.78	41.80
Nett Amount (S\$)	11,583.18	6,741.00	4,842.18	41.80

INSPECTION

Date of Assignment: 23/09/2021
 Date Inspected: 24/09/2021 Inspected At: Precise Auto Service (HQ)
 No 1 Kaki Bukit Ave 6, #02-34/36
 Singapore 417883
 Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2021)**Parts:** 143 KIA CARENS 1.7 D SUNROOF (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLC9633G)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	627.00 FL	*627.00 FL
2	1		*FRONT BUMPER SIDE RETAINER-RH	Necessary	12.00 FL	*12.00 FL
3	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
4	1		*HEAD LAMP-RH	Cracked	1,559.00 FL	*1,559.00 FL
5	1		*FOG LAMP-RH	Cracked	186.00 FL	*186.00 FL
6	1		*FRONT FENDER-RH	Dented	384.00 FL	*384.00 FL
7	1		*FRONT FENDER SPLASH SHIELD-RH	Deformed/Torn	68.00 FL	*68.00 FL
8	8		*FRONT FENDER SPLASH SHIELD CLIPS	Necessary	40.00 FL	*40.00 FL
9	1		*SIDE MIRROR-RH	Damaged	589.00 FL	*589.00 FL
10	1		*FRONT KNUCKLE ARM-RH	Bent	311.00 FL	*311.00 FL
11	1		*FRONT LOWER ARM	Bent	387.00 FL	*387.00 FL
12	1		*FRONT ABSORBER	Twisted	302.00 FL	*302.00 FL
13	1		*FRONT ABSORBER MOUNTING	Not Necessary	85.00 FL	*- FL
14	1		*FRONT WHEEL BEARING HUP	Damaged	214.00 FL	*214.00 FL
15	1		*REAR BUMPER	Cut/Deformed	510.00 FL	*510.00 FL
16	1		*REAR BUMPER SIDE RETAINER-RH	Necessary	28.00 FL	*28.00 FL
17	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
18	1		*FRONT SPORT RIM	Cut/Bent	633.60 FS	*480.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,035.60	5,797.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	540.20	531.70
Total Parts (\$\$)	5,495.40	5,265.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	120.00	60.00
2	TO CHECK WIRING SYSTEM	New	120.00	20.00
3	TO TUFF COAT AFFECTED AREAS	New	250.00	40.00
4	TO CHECK AND ADJUST COMPUTER WHEEL ALIGNMENT (BEFORE & AFTER)	New	240.00	100.00
5	TO REMOVE & REFIX FRONT RH UNDERCARRIAGE COMPONENTS & REAR AXLE BEAM	New	850.00	300.00
6	TO REMOVE & REFIX FRONT & REARRH SPORT RIM & CONTACT WHEEL BALANCING	New	350.00	0.00
7	TO RESPRAY AFFECTED AREAS	New	1,600.00	1,300.00
8	TO RENEW DAMAGED PARTS,STRAIGHTEN & REPAIR FRONT,REAR RH DOOR,REAR RH FENDER AND ALIGNED ALL PARTS	New	1,800.00	800.00
			Gross Labour Cost (\$)	5,330.00
				2,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >