

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009930/BGS3Q2**Date:** 09/03/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SKX7498U **Insured Vehicle No :** SLM7153K
 Date of Loss: 22/09/2021 Nature of Claim: TP Claim No: MFL2021D0004179

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX7498U**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZRY214318
 Reg. Date: 28/12/2015 (Man. Year: 2015) Chassis No: MR053REH104539416
 Colour: Green Odometer: 78317 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
 Front Left Side: Falken 5 mm Rear Left Side: Firenza 5 mm
 Front Right Side: Falken 5 mm Rear Right Side: Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,329.92	4,017.89	4,312.03	51.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,280.00	1,660.00	56.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,269.92	5,297.89	5,972.03	52.99
Approved Total (Overridden) (S\$)		4,250.00		
(S\$)	11,269.92	4,250.00	7,019.92	62.29
+ GST 7.00/7.00% (S\$)	788.89	297.50	491.39	62.29
Nett Amount (S\$)	12,058.81	4,547.50	7,511.31	62.29
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,094.95		
Global Sum Settlement (S\$)		5,050.00		

INSPECTION

Date of Assignment: 23/09/2021
 Date Inspected: 24/09/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Jan 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKX7498U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOTLID	Dented	881.10 FL	*755.00 FL
2	1	*REAR BOOTLID ALTIS EMBLEM	Necessary	54.10 FL	*54.10 FL
3	1	*REAR BOOTLID COROLLA EMBLEM	Necessary	50.20 FL	*50.20 FL
4	1	*REAR BOOTLID LOGO EMBLEM	Necessary	58.50 FL	*58.50 FL
5	2	*REAR BOOTLID HINGES L/R	Not Damaged	159.20 FL	*- FL
6	2	*REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R	Not Damaged	34.00 FL	*- FL
7	1	*REAR BOOTLID INNER TRIM BOARD	Not Damaged	281.85 FL	*- FL
8	1	*REAR BOOTLID LOCK STRIKER	Not Damaged	85.00 FL	*- FL
9	1	*REAR BOOTLID MECHANISM LOCK	Jammed	379.20 FL	*379.20 FL
10	1	*REAR BOOTLID OUTER CHROME HANDLE	Not Damaged	203.00 FL	*- FL
11	1	*REAR BOOTLID REFLECTOR INNER BACK RUBBER GASKET R	Not Damaged	86.20 FL	*- FL
12	1	*REAR BOOTLID REFLECTOR INNER BACK RUBBER GASKET L	Not Damaged	86.20 FL	*- FL
13	1	*REAR BOOTLID REFLECTOR L	Not Damaged	374.10 FL	*- FL
14	1	*REAR BOOTLID REFLECTOR R	Not Damaged	374.10 FL	*- FL
15	1	*REAR BOOTLID WEATHERSTRIP	Not Damaged	271.45 FL	*- FL
16	1	*REAR BUMPER	Dented	581.90 FL	*492.20 FL
17	1	*REAR BUMPER REFLECTOR L/R	Not Damaged	282.00 FL	*- FL
18	1	*REAR BUMPER REINFORCEMENT	Not Damaged	398.70 FL	*- FL
19	1	*REAR BUMPER REINFORCEMENT BRACKET R	Not Damaged	165.00 FL	*- FL
20	1	*REAR BUMPER REINFORCEMENT BRACKET L	Not Damaged	165.00 FL	*- FL
21	1	*REAR BUMPER REVERSE SENSOR L	Scratched	265.30 FL	*100.00 FL
22	1	*REAR BUMPER REVERSE SENSOR R	Scratched	265.30 FL	*100.00 FL
23	2	*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	242.20 FL	*90.00 FL
24	1	*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Damaged	715.20 FL	*- FL
25	1	*REAR BUMPER SIDE RETAINER L	Necessary	65.00 FL	*65.00 FL
26	1	*REAR BUMPER SIDE RETAINER	Necessary	65.00 FL	*65.00 FL
27	1	*REAR END PANEL	Dented	781.90 FL	*581.20 FL
28	1	*REAR END PANEL ANTENNA SENSOR	Not Damaged	175.00 FL	*- FL
29	1	*REAR END PANEL INNER TOP GARNISH	Broken	185.99 FL	*185.99 FL
30	2	*REAR TAILLAMP INNER BACK RUBBER GASKET L/R	Necessary	51.00 FL	*51.00 FL
31	1	*REAR TAILLAMP R	Broken	391.90 FL	*391.90 FL
32	1	*REAR TAILLAMP L	Broken	391.90 FL	*391.90 FL
33	2	*REAR TAILLAMP LOWER BRACKET L/R	Broken	177.40 FL	*110.00 FL
34	1	*REAR FENDER INNER TRIM R	Torn	388.00 FL	*338.00 FL
35	1	*REAR FENDER INNER TRIM L	Torn	388.00 FL	*338.00 FL
36	1	*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
37	1	*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
38	1	*SET REAR FENDER INNER TRIM CLIPS L/R	Necessary	100.00 FS	*60.00 FS
39	1	*SET REAR TAILLAMP CLIPS L/R	No such part	40.00 FS	*- FS
40	1	*REAR BUMPER LOWER SPOILER	Broken	850.00 FS	*400.00 FS
41	1	*SET REAR BOOTLID INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
42	1	*SET REAR BOOTLID OUTER CHROME HANDLE CLIPS	Necessary	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,709.89	5,167.19
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,379.97	1,149.30

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	8,329.92 4,017.89
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	80.00
2	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	100.00	0.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	140.00	0.00
4	TO RE-SPRAY PAINTING ON THE REAR BOOTLID ,REAR END PANEL,REAR FENDER (L/R) ,SPARE TYRE PANEL AND REAR BUMPER	New	1,300.00	600.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND REALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	600.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	0.00
Gross Labour Cost (\$\$)			2,940.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >