



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
NTUC INCOME INSURANCE CO-OPERATIVE LTD 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 ATTN: YON KAI JIE		Ref: CS3/INC20011978/Eqf3e2-1 Date: 12/10/2021 Code: INC	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SJT 4874U	Veh. Inspected	FBQ 4832B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1107914-003	Excess (\$)	0.00
Assign From	YON KAI JIE	Assign Date	23/09/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	YAMAHA MX KING	c.c	150
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MH3UG0750KK029778	Colour	BLUE
Odometer	25400 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	70/80-17	BRIDGESTONE	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	BRIDGESTONE	5 mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	23/10/2020	Inspection Date	03/11/2020
Survey held at	149 KAKI BUKIT AVE 1 SOON LEE INDUSTRIAL PARK		
Repairer	GARAGE 13 PTE LTD		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	