

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009935/UUCN2**Date:** 01/10/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00192282100

**Claimant Vehicle
No :** SMM565P**Insured
Vehicle No :** SFU1852U

Date of Loss: 21/09/2021

Nature of Claim: TP

Claim
No: SNM21D205353/C02/TOHHS**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMM565P**

Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A)

Engine No: CHZC29352

Reg. Date: 14/06/2019 (Man. Year: 2019)

Chassis No: WAUZZZ8V7KA064564

Colour: Red

Odometer: 15072 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size: 205/55R16

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,521.80	7,095.43	9,426.37	57.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	1,920.00	1,890.00	49.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,331.80	9,015.43	11,316.37	55.66
Approved Total (Overridden) (\$\$)		7,200.00		
Nett Amount (\$\$)	20,331.80	7,200.00	13,131.80	64.59

INSPECTION

Date of Assignment: 23/09/2021

Date Inspected: 23/09/2021 Inspected At:

 Asia Motorsports-kaki Bukit (HQ)
 15 KAKI BUKIT ROAD 4 #01-05/53 BARTLEY BIZ
 CENTRE
 Singapore 417808

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2021)
Parts:	144	AUDI A3 999cc TFSI S TRONIC (LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM565P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Dented	1,638.00 FL	*1,595.21 FL
2	1		*REAR BUMPER INNER RETAINER	Cracked	186.00 FL	*186.00 FL
3	1		*REAR BUMPER RETAINER	N/s Cracked	188.00 FL	*90.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	653.00 FL	*565.00 FL
5	2		*REAR BUMPER REFLECTORS	Not Necessary	165.00 FL	*- FL
6	1		*REAR BUMPER TOW COVER	Not Necessary	88.00 FL	*- FL
7	1		*REAR TAILGATE ASSY	Dented	1,867.00 FL	*1,867.00 FL
8	1		*REAR TAILGATE LOCK	Serviceable	267.00 FL	*- FL
9	1		*REAR TAILGATE CENTRE LOGO	Necessary	88.00 FL	*88.00 FL
10	1		*REAR TAILGATE A3 EMBLEM	Necessary	68.00 FL	*68.00 FL
11	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	288.00 FL	*- FL
12	1		*REAR TAILGATE INNER BOARD	Not Necessary	498.00 FL	*- FL
13	2		*REAR TAILGATE HINGES	Not Necessary	108.00 FL	*- FL
14	2		*REAR TAILGATE DAMPERS	Not Necessary	188.00 FL	*- FL
15	1		*REAR LEFT TAILGATE TAILLAMP	Scratched	603.00 FL	*465.00 FL
16	1		*REAR RIGHT TAILGATE TAILLAMP	Not Necessary	603.00 FL	*- FL
17	1		*REAR LEFT TAILLAMP	Cracked	898.00 FL	*627.35 FL
18	1		*REAR RIGHT TAILLAMP	Not Necessary	898.00 FL	*- FL
19	1		*REAR END PANEL	Dented/Bent	1,042.00 FL	*699.00 FL
20	1		*REAR END PANEL TOP GARNISH	Twisted	292.00 FL	*292.00 FL
21	1		*REAR EXHAUST MUFFLER ASSY	Repair	1,450.00 FL	*- FL
22	2		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	68.00 FL	*- FL
23	1		*REAR LEFT FENDER	Repair	1,044.00 FL	*- FL
24	1		*REAR LEFT QUARTER GLASS MOULDING	Not Necessary	268.00 FL	*- FL
25	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	188.00 FL	*- FL
26	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
27	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	1,200.00 FS	*200.00 FS
28	1		*REAR NO PLATE WITH GARNISH	Damaged	100.00 FS	*40.00 FS
29	1		*REAR LEFT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
30	1		*REAR LEFT QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	100.00 FS	*40.00 FS
32	1		*REAR END LOWER PANEL SEALANT	Necessary	140.00 FS	*50.00 FS
33	4		*REAR END LOWER PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
34	8		*REAR TAILGATE INNER BOARD CLIPS	Not Necessary	40.00 FS	*- FS
35	1		*REAR BUMPER LOWER SPOILER	Cut/Damaged	1,080.00 FS	*500.00 FS
36	1		*REAR BUMPER LOWER SPOILER SEALANT	Not Necessary	100.00 FS	*- FS
37	10		*REAR BUMPER LOWER SPOILER CLIPS	Not Necessary	80.00 FS	*- FS
38	1		*REAR VIEW CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,204.00	7,422.56
- List Item Discount on L Items 5.00/5.00% (\$\$)	682.20	327.13
Total Parts (\$\$)	16,521.80	7,095.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,400.00	680.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,400.00	850.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	20.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	60.00
5	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	120.00	0.00
6	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	140.00	80.00
7	TO APPLY ANTI RUST PROOFING ON REAR AFFECTED AREA	New	140.00	60.00
8	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	50.00
9	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	120.00
10	TO REMOVE AND INSTALL REAR VIEW CAMERA	New	80.00	0.00
11	TO REMOVE AND INSTALL REAR LEFT QUARTER GLASS	New	80.00	0.00
12	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$\$)			3,810.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >