

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21009941/NQCQ2**Date:** 02/09/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00088682002

**Claimant Vehicle No :** SJQ1356J **Insured Vehicle No :** GBH8176H

Date of Loss: 22/09/2021 Nature of Claim: TP Claim No: SNM21D205405/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJQ1356J**

Make & Model: HONDA CIVIC, 1.5 i-VTEC (A) Engine No: L15A71800732

Reg. Date: 25/04/2009 (Man. Year: 2008) Chassis No: MRHGM26509P020147

Colour: Grey Odometer: 149611 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15

Front Left Side: Falken 6 mm Rear Left Side: Falken 9 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,829.88	2,333.44	1,496.44	39.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	2,250.00	1,180.00	34.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,259.88</b>	<b>4,583.44</b>	<b>2,676.44</b>	<b>36.87</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,650.00</b>		
<b>(S\$)</b>	7,259.88	3,650.00	3,609.88	49.72
<b>+ GST 7.00/7.00% (S\$)</b>	508.19	255.50	252.69	49.72
<b>Nett Amount (S\$)</b>	<b>7,768.07</b>	<b>3,905.50</b>	<b>3,862.57</b>	<b>49.72</b>

INSPECTION

Date of Assignment: 28/09/2021

Date Inspected: 24/09/2021 Inspected At: Twincar Automotive Pte Ltd - Kaki Bukit (HQ)  
2 KAKI BUKIT AVENUE 2, #01-17 KAKI BUKIT  
AUTOHUB  
Singapore 417921

Estimated Period of Repair: 5.0 days

**Adjuster:** Muhammad Nazril Bin Abdullah**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2022)	
<b>Parts:</b> 144	HONDA CIVIC 1.5 i-VTEC (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SJQ1356J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	503.90 FL	*503.90 FL
2	1		*REAR BOOTLID CITY EMBLEM	Necessary	16.20 FL	*16.20 FL
3	1		*REAR BOOTLID I-VTEC EMBLEM	Necessary	22.20 FL	*22.20 FL
4	1		*REAR BOOTLID LOGO EMBLEM	Necessary	17.80 FL	*17.80 FL
5	2		*REAR BOOTLID HINGE L/R	Serviceable	128.60 FL	*- FL
6	2		*REAR BOOTLID INNER LOCK GUIDE STOPPER L/R	Serviceable	23.00 FL	*- FL
7	2		*REAR BOOTLID INNER RUBBER GUIDE STOPPER L/R	Serviceable	19.00 FL	*- FL
8	1		*REAR BOOTLID INNER TRIM BOARD	Serviceable	79.80 FL	*- FL
9	1		*REAR BOOTLID LOCK STRIKER	Deformed	27.50 FL	*27.50 FL
10	1		*REAR BOOTLID MECHANISM LOCK	Deformed	56.80 FL	*56.80 FL
11	2		*REAR BOOTLID NUMBER PLATE LAMP L/R	Not Working	36.40 FL	*36.40 FL
12	1		*REAR BOOTLID OUTER HANDLE	Serviceable	74.40 FL	*- FL
13	1		*REAR BOOTLID WEATHERSTRIP	Torn	74.40 FL	*74.40 FL
14	1		*REAR BUMPER	Deformed	463.70 FL	*463.70 FL
15	2		*REAR BUMPER SIDE BRACKET L/R	Deformed	29.60 FL	*29.60 FL
16	2		*REAR BUMPER SIDE RETAINER L/R	Deformed	29.60 FL	*29.60 FL
17	1		*REAR END PANEL	Dented	399.30 FL	*399.30 FL
18	1		*REAR END PANEL INNER TOP GARNISH	Deformed	66.60 FL	*66.60 FL
19	2		*REAR FENDER INNER TRIM BOARD L/R	Serviceable	174.60 FL	*- FL
20	1		*REAR FLOOR PANEL TOP BOARD COVER	Deformed	70.80 FL	*70.80 FL
21	1		*REAR LH FENDER	Repair	761.90 FL	*- FL
22	2		*REAR TAILLAMP INNER BACK GASKET L/R	Necessary	25.00 FL	*25.00 FL
23	2		*REAR TAILLAMP INNER PANEL L/R	Serviceable	228.00 FL	*- FL
24	2		*REAR TAILLAMP L/R	Cracked	411.40 FL	*411.40 FL
25	1		*REAR WINDSCREEN MOULDING	Necessary	65.60 FL	*65.60 FL
26	1		*SET REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
27	1		*REAR BOOTLID NUMBER PLATE	Serviceable	25.00 FS	*- FS
28	1		*REAR BOOTLID NUMBER PLATE HOLDER	Serviceable	50.00 FS	*- FS
29	1		*SET REAR BOOTLID OUTER HANDLE CLIPS	Not Necessary	50.00 FS	*- FS
30	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*80.00 FS
31	1		*SET REAR BUMPER REVERSE SENSOR	Deformed	280.00 FS	*280.00 FS
32	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
33	2		*SET REAR FENDER INNER TRIM BOARD CLIPS L/R	Not Necessary	100.00 FS	*- FS
34	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	50.00 FS	*50.00 FS
35	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,591.10</b>	<b>2,796.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	761.22	463.36
<b>Total Parts (\$\$)</b>	<b>3,829.88</b>	<b>2,333.44</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TRANFER REAR BOOTLID MICHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	50.00
2	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PROPER SENSOR	New	80.00	30.00
3	TO REMOVE ,REINSTALL WINDSCREEN (REAR)	New	150.00	120.00
4	TO REMOVE ,REINSTALL PETROL TANK (TO FR)	New	80.00	0.00
5	TO REMOVE REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	120.00	0.00
6	TO RE-SPRAY PAINTING ON THE REAR BOOTLID ,REAR END PANEL ,REAR FENDER (L/R) ,SPARE TYRE PANEL AND REAR BUMPER	New	1,300.00	1,000.00
7	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR RECONSTRUCT AND RE- ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,500.00	1,000.00
8	TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	50.00
			<b>Gross Labour Cost (S\$)</b>	<b>3,430.00</b>
				<b>2,250.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**