

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21009945/T1VCN2**Date:** 01/12/2021**REFERENCE**

Insured/Claimant: TAN INN POH BERNARD(CHEN YINBAO BERNARD) Policy No: 1900112346
Date of Loss: 17/09/2021 Nature of Claim: OD Claim No: 1276569946SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJX249E**
Make & Model: AUDI Q2, 999cc 1.0 TFSI S TRONIC (A) Engine No: CHZA91072
Reg. Date: 24/06/2019 (Man. Year: 2018) Chassis No: WAUZZZGA5KA000599
Colour: Silver Odometer: 43074 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$102,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre tread depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 10,851.00 | 7,518.32 | 3,332.68 | 30.71 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 6,912.00 | 3,182.00 | 3,730.00 | 53.96 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 17,763.00 | 10,700.32 | 7,062.68 | 39.76 |
| - Excess (S\$) | 400.00 | 400.00 | 0.00 | 0.00 |
| (S\$) | 17,363.00 | 10,300.32 | 7,062.68 | 40.68 |
| + GST 7.00/7.00% (S\$) | 1,215.41 | 721.02 | 494.39 | 40.68 |
| Nett Amount (S\$) | 18,578.41 | 11,021.34 | 7,557.07 | 40.68 |

INSPECTION

Date of Assignment: 24/09/2021
Date Inspected: 23/09/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|----------------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER-LH | Deformed | 894.00 FS | *714.80 FS |
| 2 | 1 | | *FRONT BUMPER FIXING PARTS | Not Necessary | 347.00 FS | *- FS |
| 3 | 1 | | *FRONT BUMPER AIR GUIDE GRILLE-LH | Cut | 169.00 FS | *135.20 FS |
| 4 | 1 | | *FRONT BUMPER END CAP-LH | Not Necessary | 59.00 FS | *- FS |
| 5 | 1 | | *FRONT BUMPER SPOILER | Cut | 299.00 FS | *238.80 FS |
| 6 | 1 | | *FRONT BUMPER CLOSING ELEMENT | Not Necessary | 156.00 FS | *- FS |
| 7 | 1 | | *FRONT WHEEL SPOILER-LH | Not Necessary | 34.00 FS | *- FS |
| 8 | 1 | | *FRONT BUMPER ADAPTER-LH | Not Necessary | 36.00 FS | *- FS |
| 9 | 1 | | *FRONT HEADLIGHT MOUNTING-LH | Cracked | 118.00 FS | *94.40 FS |
| 10 | 1 | | *FRONT HEADLIGHT-LH | Cut | 4,915.00 FS | *3,932.00 FS |
| 11 | 1 | | *FRONT HEADLIGHT CYLINDER WASHER-LH | Not Necessary | 142.00 FS | *- FS |
| 12 | 1 | | *FRONT HEADLIGHT WASHER HOSE | Not Necessary | 182.00 FS | *- FS |
| 13 | 1 | | *FRONT BUMPER GUIDE SECTION-LH | Not Necessary | 36.00 FS | *- FS |
| 14 | 2 | | *FRONT WHEEL ARCH COVER-LH/RH | N/s Cut/O/s Deformed | 644.00 FS | *514.40 FS |
| 15 | 1 | | *FRONT FENDER-LH | Bent | 1,147.00 FS | *917.60 FS |
| 16 | 1 | | *FRONT FENDER ATTACHMENT PART | Not Necessary | 40.00 FS | *- FS |
| 17 | 1 | | *FRONT FENDER TOP BRACKET-LH | Not Necessary | 48.00 FS | *- FS |
| 18 | 1 | | *FRONT FENDER CENTER BRACKET-LH | Not Necessary | 16.00 FS | *- FS |
| 19 | 1 | | *FRONT FENDER REAR BRACKET-LH | Not Necessary | 23.00 FS | *- FS |
| 20 | 1 | | *FRONT FENDER BRACE | Bent | 44.00 FS | *34.88 FS |
| 21 | 1 | | *FRONT WHEEL HOUSING LINER-LH | Deformed | 196.00 FS | *156.40 FS |
| 22 | 1 | | *FRONT WHEEL HOUSING LINER ATTACHMENT PART | Not Necessary | 57.00 FS | *- FS |
| 23 | 1 | | *FRONT ALUMINIUM RIM-LH | Cut | 949.00 FS | *758.80 FS |
| 24 | 1 | | *SUNDRIES | Necessary | 300.00 FS | *21.04 FS |

F=Franchise part. S=SpcNett.

Total Parts (S\$) 10,851.00 7,518.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY | New | 360.00 | 360.00 |
| 2 | TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE | New | 400.00 | 250.00 |
| 3 | TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR | New | 280.00 | 0.00 |
| 4 | TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED | New | 2,400.00 | 1,100.00 |
| 5 | TO RESPRAY FRONT BUMPER,LHS FRONT FENDER AND LHS FRONT DOOR | New | 3,000.00 | 1,000.00 |
| 6 | TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT | New | 280.00 | 280.00 |
| 7 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| Gross Labour Cost (\$\$) | | | 6,912.00 | 3,182.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >