

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009946/UQC2**Date:** 13/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00020102100	
Claimant Vehicle No :	SKV866Y	Insured Vehicle No :	GBE6730L	
Date of Loss:	23/09/2021	Nature of Claim:	TP	Claim No: SNM21D205431/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV866Y	Engine No:	4J11BC8415
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	GF7W0601626
Reg. Date:	14/06/2019 (Man. Year: 2019)	Odometer:	58226 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,874.00	7,140.00	2,734.00	27.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,460.00	7,030.00	3,430.00	32.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	20,334.00	14,170.00	6,164.00	30.31
+ GST 7.00/7.00% (\$\$)	1,423.38	991.90	431.48	30.31
Nett Amount (\$\$)	21,757.38	15,161.90	6,595.48	30.31

INSPECTION

Date of Assignment:	24/09/2021	
Date Inspected:	27/09/2021 Inspected At:	Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ) 330 Ubi Road 3 Singapore 408650
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Oct 2021)
Parts:	M1-SUV	MITSUBISHI OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV866Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GLASS,TAILGATE WINDO	Necessary	657.00 FS	*657.00 FS
2	1		*UPR DAM,TAILGATE	Necessary	13.00 FS	*13.00 FS
3	2		*SIDE DAM,TAILGATE	Necessary	54.00 FS	*54.00 FS
4	1		*LWR DAM,TAIL GATE	Necessary	41.00 FS	*41.00 FS
5	4		*FASTENER,WINDSHIELD	Necessary	24.00 FS	*24.00 FS
6	2		*STOPPER,WINDSHIELD G	Necessary	6.00 FS	*6.00 FS
7	1		*PANEL ASSY,TAILGATE	Badly Dented	989.00 FS	*989.00 FS
8	1		*GARNISH,TAILGATE	Scratched	496.00 FS	*496.00 FS
9	1		*MARK,OUTLANDER	Necessary	95.00 FS	*95.00 FS
10	1		*LATCH,TAILGATE	Not Necessary	475.00 FS	*- FS
11	1		*STRIKER TAILGATE LAT	Not Necessary	19.00 FS	*- FS
12	1		*WEATHERSTRIP,TAILGA	Not Necessary	213.00 FS	*- FS
13	1		*LH RR OTR LAMP ASSY	Cracked	603.00 FS	*603.00 FS
14	1		*LH RR INR LAMP ASSY	Cracked	506.00 FS	*506.00 FS
15	1		*RH RR OTR LAMP ASSY	Not Necessary	603.00 FS	*- FS
16	1		*RH RR INR LAMP ASSY	Not Necessary	506.00 FS	*- FS
17	1		*FACE,RR BUMPER	Dented/Deformed	811.00 FS	*811.00 FS
18	10		*CLIP,BUMPER	Necessary	40.00 FS	*40.00 FS
19	1		*LH SIDE BRACKET,RR	Bent	12.00 FS	*12.00 FS
20	1		*RH SIDE BRACKET,RR	Not Necessary	12.00 FS	*- FS
21	1		*REAR BUMPER PLATE	Bent	192.00 FS	*192.00 FS
22	1		*EXTENSION,RR BUMPER	Deformed	292.00 FS	*292.00 FS
23	1		*LH REFLECTOR,TAIL LA	Not Necessary	100.00 FS	*- FS
24	1		*RH REFLECTOR,TAIL LA	Not Necessary	100.00 FS	*- FS
25	1		*OUTLANDER 2019 BODY	Necessary/Warped	1,554.00 FS	*1,554.00 FS
26	1		*ANTENNA,KEYLESS OPE	Cracked	96.00 FS	*96.00 FS
27	1		*BUZZER,KEYLESS OPER	Cracked	91.00 FS	*91.00 FS
28	1		*PANEL,RR END	Repair	326.00 FS	*- FS
29	1		*LH RR LWR EXTENSION	Dented	78.00 FS	*78.00 FS
30	1		*HARNESS,RR END	Torn/Cracked	90.00 FS	*90.00 FS
31	1		*REAR LICENSE PLATE WITH CASING	Bent	50.00 FS	*50.00 FS
32	1		*C&C LOGO	Necessary	50.00 FS	*20.00 FS
33	1		*MIVEC EMBLEM	Necessary	50.00 FS	*50.00 FS
34	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*280.00 FS
35	1		*REVERSE CAMERA LENS	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **9,874.00** **7,140.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSTIC/SCANNING	New	250.00	250.00
2	TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS	New	100.00	80.00
3	TO REPLACE TAILGATE GLASS & MLDGS	New	300.00	300.00
4	TO INSTALL RIKECOOL SOLAR FILM ON NEW TAILGATE GLASS	New	200.00	200.00
5	TO APPLY SEALANT KIT ON NEW TAILGATE GLASS	New	100.00	100.00
6	TO TRANSFER TAILGATE COMPONENTS & MECHANISM PARTS	New	640.00	320.00
7	TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	640.00	320.00
8	TO APPLY SEALANT KIT IN NEW & REPAIR PANELS	New	200.00	100.00
9	TO REPLACE TAILGATE, EMBLEM, TAIL LAMPS, REAR BUMPER, CLIPS, BRACKETS, REFLECTOR LAMPS, BUZZER, ANTENNA, ETC-TO CUT & WELD REAR END PANEL- TO REPAIR LHR OTR FENDER, STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	4,480.00	2,560.00
10	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	2,750.00	2,200.00
11	TO REPLACE & RESPRAY BODY KIT	New	800.00	600.00
Gross Labour Cost (\$\$)			10,460.00	7,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >