

(08/11/13) wef
ASS. REC. BY: Marcus


REF: CS/CT121009946/Ugc

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SKV866Y
at Workshop m/s: CRC Ubi, Wm
of _____
Insured: GAE6730C
Policy No. _____
Claims No. SNM21D205431/C02
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: \$95k.
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 6 days Res.: Yes or No
Lum Sum: 151 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

5782
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKV866Y Yr Regn: 14/6/19
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or Car
Make: mit outlander c.c. 1998
Colour: black A/C: Insured / Std / NI / NA
Sp. Reading: 58226 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: GF7W0601626
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/55 R18
R: _____

BS / QUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

| | | | | | |
|--------|----------------|----|--------|----------------|----|
| Front | <u>6</u> | mm | Rear | <u>6</u> | mm |
| R/Bal. | <u>6</u> | mm | R/Bal. | <u>6</u> | mm |
| L/Bal. | <u>6</u> | mm | L/Bal. | <u>6</u> | mm |
| D.O.A. | <u>23/9/21</u> | | D.O.I. | <u>27/9/21</u> | |

Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 207/11k.
have video 17A \$55424

7/10/21 confirmed NP \$14170.00 with Ren (Red \$6164, 30%)

Date/Time, File Pass to? ☐ : Preli. Report

1) 11/10 Typist ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

TOTAL

Report Format : MER-TP

Lump Sum / I.B.I.: (\$ 14170)



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

| Invoice Name & Address | Owner Name & Vehicle Info | |
|---|---------------------------|-------------------------------------|
| CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111 | Cust No/Name | /Mr Seet Jef Frey (xue Yuehui) |
| | Reg No/Reg Date | SKV866Y / 14/06/2019 |
| | Date In/Mileage | 23/09/2021/ 57930 |
| | Chassis No | GF7W0601626 |
| | Engine No | 4J11BC8415 |
| | Make/Model | MIT/19MY OUTLANDER 2.0 SPORTS (994) |
| | Colour/Trim | X04 / BK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | |
|---|--------|-------------------|-----|---------------|--------|------------|--------------|
| F0000018 | Credit | 23/09/2021/ 15:09 | DS | 303 / Renemer | 19220 | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% Amount |
| S MIPNT88088 | | | | | | | 250.00 ✓ |
| DIAGNOSTIC/SCANNING | | | | | | | |
| S MIPNT88088 | | | | | | 80 | 100.00 ✓ |
| TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS | | | | | | | |
| S MIPNT88088 | | | | | | | 300.00 ✓ |
| TO REPLACE TAILGATE GLASS & MLDGS | | | | | | | |
| S MIPNT88088 | | | | | | 1M | 200.00 ✓ |
| TO INSTALL RIKECOOL SOLAR FILM ON NEW TAILGATE GLASS | | | | | | | |
| S MIPNT88088 | | | | | | | 100.00 ✓ |
| TO APPLY SEALANT KIT ON NEW TAILGATE GLASS | | | | | | | |
| S MIPNT88088 | | | | | | 320 | 640.00 ✓ |
| TO TRANSFER TAILGATE COMPONENTS & MECHANISM PARTS | | | | | | | |
| S MIPNT88088 | | | | | | 320 | 640.00 ✓ |
| TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS | | | | | | | |
| S MIPNT88088 | | | | | | 100 | 200.00 ✓ |
| TO APPLY SEALANT KIT IN NEW & REPAIR PANELS | | | | | | | |
| S MIPNT88088 | | | | | | | 4480.00 ✓ |
| TO REPLACE TAILGATE, EMBLEM, TAIL LAMPS, REAR BUMPER, CLIPS, BRACKETS, REFLECTOR LAMPS, BUZZER, ANTENNA, ETC | | | | | 640 | 2560 | |
| -TO CUT & WELD REAR END PANEL -TO REPAIR LHR OTR FENDER STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS | | | | | 220 | 2200 | |
| S MIPNT98088 | | | | | | | 2750.00 ✓ |
| SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS | | | | | | | |
| S MIPNT88088 | | | | | | 600 | 800.00 ✓ |
| TO REPLACE & RESPRAY BODY KIT | | | | | | | |
| S MIPNT88088 | | | | | | 11 | 350.00 X |
| REVERSE CAMERA LENS | | | | | | | |
| S MIPNT88088 | | | | | | 280.00 | 280.00 ✓ |
| REVERSE SENSOR SET | | | | | | | |
| S MIPNT88088 | | | | | | | 50.00 ✓ |
| REAR LICENSE PLATE WITH CASING | | | | | | | |
| M SUNDRY | | | | | | 20 | 50.00 ✓ |

Confirm & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

| Invoice Name & Address | Owner Name & Vehicle Info |
|--|--|
| CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. | Cust No/Name /Mr Seet Jef Frey (xue Yuehui) |
| Contact No 63896111 | Reg No/Reg Date SKV866Y / 14/06/2019 |
| | Date In/Mileage 23/09/2021/ 57930 |
| | Chassis No GF7W0601626 |
| | Engine No 4J11BC8415 |
| | Make/Model MIT/19MY OUTLANDER 2.0 SPORTS (994) |
| | Colour/Trim X04 / BK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|--|-----------------------|-------------------|------------|---------------|---------|
| F0000018 | Credit | 23/09/2021/ 15:09 | DS | 303 / Renemer | 19220 |
| Description of Goods / Services | | Qty | Unit Price | Disc% | Amount |
| C & C LOGO | | | | | 50.00 |
| M SUNDRY | | | | | |
| MIVEC EMBLEM | | | | | |
| M JJ5805A759 | GLASS, TAILGATE WINDO | 1.00 | 657.00 | 0.00 | 657.00 |
| M JJ5805A316 | UPR DAM, TAILGATE | 1.00 | 13.00 | 0.00 | 13.00 |
| M JJ5805A315 | SIDE DAM, TAILGATE | 2.00 | 27.00 | 0.00 | 54.00 |
| M JJ5805A317 | LWR DAM, TAIL GATE | 1.00 | 41.00 | 0.00 | 41.00 |
| M JJMB814447 | FASTENER, WINDSHIELD | 4.00 | 6.00 | 0.00 | 24.00 |
| M JJMR462285 | STOPPER, WINDSHIELD G | 2.00 | 3.00 | 0.00 | 6.00 |
| M JJ5801B675 | PANEL ASSY, TAILGATE | 1.00 | 989.00 | 0.00 | 989.00 |
| M JJ5817A265XA | GARNISH, TAILGATE | 1.00 | 496.00 | 0.00 | 496.00 |
| M JJ7415A401 | MARK, OUTLANDER | 1.00 | 95.00 | 0.00 | 95.00 |
| M JJ5808A135 | LATCH, TAILGATE | 1.00 | 475.00 | 0.00 | 475.00 |
| M JJMN170675 | STRIKER, TAILGATE LAT | 1.00 | 19.00 | 0.00 | 19.00 |
| M JJ5815A067 | WEATHERSTRIP, TAILGA | 1.00 | 213.00 | 0.00 | 213.00 |
| M JJ8330B173 | LH RR OTR LAMP ASSY, | 1.00 | 603.00 | 0.00 | 603.00 |
| M JJ8331A179 | RH RR INR LAMP ASSY, | 1.00 | 506.00 | 0.00 | 506.00 |
| M JJ8330B174 | LH RR OTR LAMP ASSY, | 1.00 | 603.00 | 0.00 | 603.00 |
| M JJ8331A180 | RH RR INR LAMP ASSY, | 1.00 | 506.00 | 0.00 | 506.00 |
| M JJ6410F219 | FACE, RR BUMPER | 1.00 | 811.00 | 0.00 | 811.00 |
| M JJMR200300 | CLIP, BUMPER | 10.00 | 4.00 | 0.00 | 40.00 |
| M JJ6410D336 | LH SIDE BRACKET, RR | 1.00 | 12.00 | 0.00 | 12.00 |
| M JJ6410D337 | RH SIDE BRACKET, RR | 1.00 | 12.00 | 0.00 | 12.00 |
| M JJMZ574707EX | REAR BUMPER PLATE | 1.00 | 192.00 | 0.00 | 192.00 |
| M JJ6415A117HA | EXTENSION, RR BUMPER | 1.00 | 292.00 | 0.00 | 292.00 |
| M JJ8336A153 | LH REFLECTOR, TAIL LA | 1.00 | 100.00 | 0.00 | 100.00 |
| M JJ8336A154 | RH REFLECTOR, TAIL LA | 1.00 | 100.00 | 0.00 | 100.00 |
| M JJMZ576000A | OUTLANDER 2019 BODY | 1.00 | 1554.00 | 0.00 | 1554.00 |
| M JJ8637B115 | ANTENNA, KEYLESS OPE | 1.00 | 96.00 | 0.00 | 96.00 |
| M JJ8637A176 | BUZZER, KEYLESS OPE | 1.00 | 91.00 | 0.00 | 91.00 |
| M JJ5257A967 | PANEL, RR END | 1.00 | 326.00 | 0.00 | 326.00 |
| Z NOTES | | | | | |
| ACCIDENT ON 23/09/2021 ALONG SIMS PLACE TURNING LEFT TO LOR 17 GEYLANG | | | | | |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

| Invoice Name & Address | Owner Name & Vehicle Info |
|---|--|
| CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111 | Cust No/Name /Mr Seet Jef Frey (xue Yuehui) Reg No/Reg Date SKV866Y / 14/06/2019 Date In/Mileage 29/09/2021/ 58424 Chassis No GF7W0601626 Engine No 4J11BC8415 Make/Model MIT/19MY OUTLANDER 2.0 SPORTS (994) Colour/Trim X04 / BK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|------------|--------|-------------------|-----|---------------|--------|
| F0000018 | Credit | 04/10/2021/ 13:27 | DS | 303 / Renemer | 19220 |

| | Description of Goods/Services | Qty | Unit Price | Disc% | Amount |
|--------------|--------------------------------|------|------------|-------|--------|
| P JJ5301H593 | LH RR LWR EXTENSION, <i>DS</i> | 1.00 | 78.00 | 0.00 | 78.00 |
| M JJ8510J305 | HARNESS, RR END <i>torr/cr</i> | 1.00 | 90.00 | 0.00 | 90.00 |
| Z NOTES | | | | | |
| | SUPPLEMENTARY ITEMS | | | | |

Estimate

| | | |
|--|-------------------|--------|
| Confirm & accepted by | Parts | 168.00 |
| | Labour | 0.00 |
| | Standard Menu | 0.00 |
| | Specialist Job | 0.00 |
| | Others (Lub, etc) | 0.00 |
| | Sundry | 0.00 |
| Authorized signatory and company stamp | Total (w/o GST) | 168.00 |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

| Invoice Name & Address | Owner Name & Vehicle Info | | | | | | | | | | | | | | |
|---|--|--------------|--------------------------------|-----------------|----------------------|-----------------|-------------------|------------|-------------|-----------|------------|------------|-------------------------------------|-------------|----------|
| CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111 | <table> <tr> <td>Cust No/Name</td><td>/Mr Seet Jef Frey (xue Yuehui)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SKV866Y / 14/06/2019</td></tr> <tr> <td>Date In/Mileage</td><td>29/09/2021/ 58424</td></tr> <tr> <td>Chassis No</td><td>GF7W0601626</td></tr> <tr> <td>Engine No</td><td>4J118C8415</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY OUTLANDER 2.0 SPORTS (994)</td></tr> <tr> <td>Colour/Trim</td><td>X04 / BK</td></tr> </table> | Cust No/Name | /Mr Seet Jef Frey (xue Yuehui) | Reg No/Reg Date | SKV866Y / 14/06/2019 | Date In/Mileage | 29/09/2021/ 58424 | Chassis No | GF7W0601626 | Engine No | 4J118C8415 | Make/Model | MIT/19MY OUTLANDER 2.0 SPORTS (994) | Colour/Trim | X04 / BK |
| Cust No/Name | /Mr Seet Jef Frey (xue Yuehui) | | | | | | | | | | | | | | |
| Reg No/Reg Date | SKV866Y / 14/06/2019 | | | | | | | | | | | | | | |
| Date In/Mileage | 29/09/2021/ 58424 | | | | | | | | | | | | | | |
| Chassis No | GF7W0601626 | | | | | | | | | | | | | | |
| Engine No | 4J118C8415 | | | | | | | | | | | | | | |
| Make/Model | MIT/19MY OUTLANDER 2.0 SPORTS (994) | | | | | | | | | | | | | | |
| Colour/Trim | X04 / BK | | | | | | | | | | | | | | |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|------------|--------|-------------------|-----|---------------|--------|
| F0000018 | Credit | 04/10/2021/ 13:35 | DS | 303 / Renemer | 19220 |

| Description of Goods // Services | Qty | Unit Price | Disc% | Amount |
|---|-----|------------|-------|---------|
| S MIPNT88088 DIAGNOSTIC/SCANNING | | | | 250.00 |
| S MIPNT88088 TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS | | | | 80.00 |
| S MIPNT88088 TO REPLACE TAILGATE GLASS & MLDGS | | | | 300.00 |
| S MIPNT88088 TO INSTALL RIKECOOL SOLAR FILM ON NEW TAILGATE GLASS | | | | 200.00 |
| S MIPNT88088 TO APPLY SEALANT KIT ON NEW TAILGATE GLASS | | | | 100.00 |
| S MIPNT88088 TO TRANSFER TAILGATE COMPONENTS & MECHANISMS/PARTS | | | | 320.00 |
| S MIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS | | | | 320.00 |
| S MIPNT88088 TO APPLY SEALANT KIT IN NEW & REPAIR PANELS | | | | 100.00 |
| S MIPNT88088 TO REPLACE TAILGATE, EMBLEM, LH TAIL LAMPS, REAR BUMPER, CLIPS, BRACKETS, EXTENSION BUMPER, BUZZER, ANTENNA, HARNESS RR BUMPER. -TO CUT & WELD LH LWR EXTSN -TO REPAIR LHR FENDER & REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS | | | | 2560.00 |
| S MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS (TAILGATE, REAR BUMPER, LHR OTR FENDER, RR END PANEL & LH LWR EXTENSION) | | | | 2200.00 |
| S MIPNT88088 TO REPLACE & RESPRAY BODY KIT | | | | 600.00 |
| S MIPNT88088 REVERSE SENSOR SET | | | | 280.00 |
| S MIPNT88088 REAR LICENSE PLATE WITH CASING | | | | 50.00 |
| M SUNDRY C & C LOGO | | | | 20.00 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

| Invoice Name & Address | Owner Name & Vehicle Info |
|---|--|
| CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111 | Cust No/Name /Mr Seet Jef Frey (xue Yuehui) Reg No/Reg Date SKV866Y / 14/06/2019 Date In/Mileage 29/09/2021/ 58424 Chassis No GF7W0601626 Engine No 4J11BC8415 Make/Model MIT/19MY OUTLANDER 2.0 SPORTS (994) Colour/Trim X04 / BK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | | |
|---------------------------------|--|-----------------------|-------|---------------|--------|------------|-------|--------|-------|
| F0000018 | Credit | 04/10/2021/ 13:35 | DS | 303 / Renemer | 19220 | | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount | |
| M | SUNDRY | | | | | | | | 50.00 |
| | MIVEC EMBLEM | | | | | | | | |
| P | JJ5805A759 | GLASS, TAILGATE WINDO | 1.00 | 657.00 | 0.00 | 657.00 | | | |
| P | JJ5805A316 | UPR DAM, TAILGATE | 1.00 | 13.00 | 0.00 | 13.00 | | | |
| P | JJ5805A315 | SIDE DAM, TAILGATE | 2.00 | 27.00 | 0.00 | 54.00 | | | |
| P | JJ5805A317 | LWR DAM, TAIL GATE | 1.00 | 41.00 | 0.00 | 41.00 | | | |
| P | JJMB814447 | FASTENER, WINDSHIELD | 4.00 | 6.00 | 0.00 | 24.00 | | | |
| P | JJMR462285 | STOPPER, WINDSHIELD G | 2.00 | 3.00 | 0.00 | 6.00 | | | |
| P | JJ58018675 | PANEL ASSY, TAILGATE | 1.00 | 989.00 | 0.00 | 989.00 | | | |
| P | JJ5817A265WA | GARNISH, TAILGATE | 1.00 | 496.00 | 0.00 | 496.00 | | | |
| P | JJ7415A401 | MARK, OUTLANDER | 1.00 | 95.00 | 0.00 | 95.00 | | | |
| M | JJ83308173 | LH RR OTR LAMP ASSY | 1.00 | 603.00 | 0.00 | 603.00 | | | |
| P | JJ8331A179 | LH RR INR LAMP ASSY | 1.00 | 506.00 | 0.00 | 506.00 | | | |
| P | JJ6410F219 | FACE, RR BUMPER | 1.00 | 811.00 | 0.00 | 811.00 | | | |
| P | JJMR328954 | CLIP, BUMPER | 10.00 | 4.00 | 0.00 | 40.00 | | | |
| P | JJ6410D336 | LH SIDE BRACKET, RR | 1.00 | 12.00 | 0.00 | 12.00 | | | |
| P | JJ6410D336 | REAR BUMPER PLATE | 1.00 | 192.00 | 0.00 | 192.00 | | | |
| P | JJMJZ574707EX | OUTLANDER 2019 BODY | 1.00 | 1554.00 | 0.00 | 1554.00 | | | |
| P | JJMJZ576000A | ANTENNA, KEYLESS OPE | 1.00 | 96.00 | 0.00 | 96.00 | | | |
| P | JJ8637B115 | BUZZER, KEYLESS OPER | 1.00 | 91.00 | 0.00 | 91.00 | | | |
| P | JJ8637A176 | LH RR LWR EXTENSION, | 1.00 | 78.00 | 0.00 | 78.00 | | | |
| P | JJ5301H593 | HARNESS, RR END | 1.00 | 90.00 | 0.00 | 90.00 | | | |
| P | JJ8510J305 | EXTENSION, RR BUMPER | 1.00 | 292.00 | 0.00 | 292.00 | | | |
| P | JJ85010W001P | | | | | | | | |
| Z | NOTES | | | | | | | | |
| | ACCIDENT ON 23/09/2021 ALONG SIMS PLACE TURNING LEFT TO LOR 17 GEYLANG | | | | | | | | |
| | OWNER CLAIMING THIRD PARTY | | | | | | | | |
| | LOSS OF RENTAL | | | | | | | | |
| | TP#: GBE6730L | TP INS: CHINA TAIPING | | | | | | | |
| Z | NOTES | | | | | | | | |
| | FINALIZATION (NO. OF TOTAL REPAIR DAYS - 8 DAYS) | | | | | | | | |
| | ATTENTION TO: MR. MARCUS CHUA | | | | | | | | |

Confirm & accepted by

| | |
|-------------------|-----------|
| Parts | 6,740.00 |
| Labour | 0.00 |
| Standard Menu | 0.00 |
| Specialist Job | 7,360.00 |
| Others (Lub, etc) | 0.00 |
| Sundry | 70.00 |
| Total (w/o GST) | 14,170.00 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.