



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 9097H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRT BUMPER	DEFORMED	453.80	453.80
1	FRT BUMPER REINFORCEMENT	DENTED	367.20	367.20
1	FRT BUMPER LOGO	NECESSARY	60.10	60.10
1	FRT BUMPER GRILLE	DEFORMED	121.90	121.90
2	FRT BUMPER SIDE RETAINERS	NECESSARY	120.20	120.20
1	HEADLAMP RH	CRACKED	691.50	691.50
	LESS 25% DISCOUNT		-453.68	-453.68
			1,361.02	1,361.02
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRT LOWER SPOILER (SN)	DEFORMED	500.00	400.00
1	FRT GRILLE (SN)	DEFORMED	280.00	200.00
1	FRT GRILLE TRD EMBLEM (SN)	NOT NECESSARY	50.00	-
1	SET FRT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	SET FRT BUMPER SIDE PROTECTOR (SN)	NECESSARY	150.00	100.00
1	FRT NUMBER PLATE (SN)	DENTED	50.00	50.00
			1,090.00	780.00
<b><u>LABOUR</u></b>				
	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.		500.00	400.00
	TO SPRAY PAINTING.		500.00	400.00
	TO CHECK WIRING.		50.00	30.00
			1,050.00	830.00
<b>GRAND TOTAL</b>			<b>3,501.02</b>	<b>2,971.02</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,350.00</b>
---------------------------------------------------------------------------------	--	--	-----------------

Report Ref No. CS/AGI21009947/Aqf3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.