

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21009951/KUF3E2

Date: 07/10/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001239649

Claimant Vehicle No : SJM851Z

Insured Vehicle No : SLW93T

Date of Loss: 23/09/2021

Nature of Claim: TP

Claim No: 263093

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM851Z**

Make & Model: HONDA STREAM, 1.8 X (A)

Engine No: R18A1793248

Reg. Date: 19/12/2008 (Man. Year: 2008)

Chassis No: RN61084067

Colour: Metallic Pearl White

Odometer: 266283 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Tourador 9 mm

Rear Left Side: Pirelli 9 mm

Front Right Side: Tourador 9 mm

Rear Right Side: Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,650.52	3,441.66	3,208.86	48.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	1,520.00	1,000.00	39.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,170.52	4,961.66	4,208.86	45.90
Approved Total (Overridden) (S\$)		3,950.00		
Nett Amount (S\$)	9,170.52	3,950.00	5,220.52	56.93

INSPECTION

Date of Assignment: 24/09/2021

Date Inspected: 27/09/2021 Inspected At:

Massive Trading & Auto
Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2
Singapore 569541

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2021)
Parts:	M1-MPV	HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM851Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL-GATE ASSY	Bent	985.70 FL	*903.20 FL
2	1		*REAR TAIL-GATE OUTER HANDLE	Cracked	265.70 FL	*181.90 FL
3	1		*REAR NO PLATE LAMP	N/S Dented	90.20 FL	*45.10 FL
4	1		*REAR TAIL-GATE EMBLEM STREAM	Necessary	45.60 FL	*45.60 FL
5	1		*REAR TAIL-GATE INNER TRIM BOARD	Mtg Cracked	285.70 FL	*285.70 FL
6	1		*REAR TAIL-GATE INNER LOCK	Dented	255.30 FL	*195.20 FL
7	1		*REAR TAIL-GATE GLASS MOULDING	Necessary	55.20 FL	*55.20 FL
8	1		*REAR TAIL-LAMP ASSY	N/S Cracked	970.20 FL	*388.50 FL
9	1		*REAR WIPER MOTOR	Jammed	485.90 FL	*481.90 FL
10	1		*REAR END PANEL	Bent	482.30 FL	*353.10 FL
11	1		*REAR END PANEL INNER GARNISH	Mtg Distorted	185.70 FL	*185.70 FL
12	1		*REAR BOOT RUBBER (\$165.80) (50%)	Distorted / Dented	132.64 FS	*82.90 FS
13	2		*REAR FENDER INNER TRIM BOARD	Serviceable	910.40 FL	*- FL
14	1		*REAR BOOT FLOOR PANEL TOP COVER BOARD	Serviceable	385.70 FL	*- FL
15	1		*REAR BUMPER	Cracked	950.70 FL	*683.60 FL
16	2		*REAR BUMPER SIDE RETAINER	Serviceable	130.40 FL	*- FL
17	2		*REAR BUMPER BRACKET	Repair	97.20 FL	*- FL
18	1		*REAR EXHAUST SILENCER	Repair	846.70 FL	*- FL
19	1		*REAR REVERSE CAMERA	Dented	450.00 FS	*250.00 FS
20	1		*REAR WINDSCREEN SEALANT	Necessary	55.00 FS	*40.00 FS
21	1		*REAR NO PLATE	Serviceable	45.00 FS	*- FS
22	10		*REAR BUMPER CLIP	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,136.24	4,202.60
- List Item Discount on L Items 20.00/20.00% (\$)	1,485.72	760.94
Total Parts (\$)	6,650.52	3,441.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING	New	1,000.00	600.00
2	TO PUTTY AND SPRAY PAINT	New	1,000.00	660.00
3	CHECK AND RECONNECT WIRING	New	40.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	120.00	60.00
5	REMOVE / RENEW REAR WINDSCREEN GLASS	New	120.00	120.00
6	REMOVE / REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	120.00	60.00
7	REMOVE / RENEW REAR EXHAUST SILENCER	New	120.00	0.00
Gross Labour Cost (\$\$)			2,520.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >