

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21009952/ETCN2**Date:** 14/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00110902101		
<b>Claimant Vehicle No :</b>	CB6364P	<b>Insured Vehicle No :</b>	SJM5786X		
Date of Loss:	22/09/2021	Nature of Claim:	TP	Claim No:	SNM21D205429/C02/THAMYL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>CB6364P</b>		
Make & Model:	TOYOTA HIACE, 3.0 COMMUTER GL (A)	Engine No:	1KD1799714
Reg. Date:	03/06/2008 (Man. Year: 2008)	Chassis No:	KDH2230003477
Colour:	Silver	Odometer:	677959 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,019.05	3,582.51	3,436.54	48.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,570.00	1,690.00	880.00	34.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,589.05</b>	<b>5,272.51</b>	<b>4,316.54</b>	<b>45.02</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,200.00</b>		
<b>(\$\$)</b>	9,589.05	4,200.00	5,389.05	56.20
<b>+ GST 7.00/7.00% (\$\$)</b>	671.23	294.00	377.23	56.20
<b>Nett Amount (\$\$)</b>	<b>10,260.28</b>	<b>4,494.00</b>	<b>5,766.28</b>	<b>56.20</b>

**INSPECTION**

Date of Assignment:	03/10/2021		
Date Inspected:	27/09/2021	Inspected At:	Connect3 (woodlands) (HQ) 566 Woodlands Road Singapore 728697
Estimated Period of Repair:	5.0 days		

**Adjuster:** CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 13 Oct 2021)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 COMMUTER GL (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for CB6364P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	489.70 F	*489.70 FL
2	10		*REAR BUMPER CLIPS	Necessary	35.00 F	*30.00 FL
3	2		*REAR BUMPER BRACKET	Broken	128.00 F	*128.00 FL
4	1		*REAR INNER END PANEL	Dented	559.90 F	*559.90 FL
5	1		*REAR TAILGATE	Dented	2,189.30 F	*2,189.30 FL
6	1		*REAR TAILGATE W/STRIP	Torn	391.20 F	*391.20 FL
7	1		*OUTER END PANEL	Dented	635.25 F	*635.25 FL
8	1		*REAR RH TAILLAMP	Not Necessary	210.40 F	*- FL
9	1		*REAR WINDSCREEN	Not Necessary	1,565.30 F	*- FL
10	1		*EXHAUST TIP	Not Necessary	455.00 F	*- FL
11	1		*PULL TO OPEN STICKER	Not Necessary	15.00 F	*- FL
12	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
13	1		*HIACE EMBLEM	Necessary	75.00 FS	*60.00 FS
14	1		*TOYOTA EMBLEM	Necessary	65.00 FS	*65.00 FS
15	1		*GL EMBLEM	Necessary	95.00 FS	*70.00 FS
16	1		*EMERGENCY DOOR STICKER	Necessary	15.00 FS	*15.00 FS
17	2		*SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>7,019.05</b>	<b>4,688.35</b>
<b>- List Item Discount on L Items 0.00/25.00% (S\$)</b>	0.00	1,105.84
<b>Total Parts (S\$)</b>	<b>7,019.05</b>	<b>3,582.51</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TRANSFER REAR TAILGATE FITTINGS	New	150.00	50.00
2	REMOVE & REFIT REAR WINDSCREEN TO ASSIST REPAIR	New	200.00	120.00
3	CHECK WIRING	New	20.00	20.00
4	SPRAY PAINTING WITH COMPANY NAME	New	1,000.00	600.00
5	LABOUR CHARGES	New	1,200.00	900.00
<b>Gross Labour Cost (\$)</b>			<b>2,570.00</b>	<b>1,690.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >