

REG BY:

Steve

DATE:

CS/CTI 21009.952/ETC

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bol. or Market Value:

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs. days Res.: Yes or No

Lum Sum: % 3 Vol.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

CB 6364P

Yr Rogn:

3/6/08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace Commander

c.c

1982

Colour

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

677959

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KDH2230003477

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

F:

R:

U

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bol.

4

mm

R/Bol.

4

mm

L/Bol.

4

mm

L/Bol.

4

mm

D.O.A.

27/9/21

D.O.I.

27/9/21

Survey held at

corner 3

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooltop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NAV - 40K

lump sum \$4200, 5days
red:5389.05;

Date/Time, File Pass to?

☐

: Prel. Report

1/

☐

: Final Report

Date/Time, File Return to?

2/

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp \$

☐

: Interview \$

☐

: Tech. Inve \$

☐

: Wheel Eng \$

Survey Fee:

Transportation:

\$ + RS. \$

Food:

Other:

Total:

Request Form:

Letter Sign / U/C:

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT21/CB6364P/TPC

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

QUOTATION

Dear Sir,

Cost of Repair to Vehicle CB6364P

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Rear bumper / BR	1	489.70	489.70
2.	Rear bumper clips / APC	10	3.50	30 35.00
3.	Rear bumper bracket / BR	2	64.00	128.00
4.	Rear inner end panel ?	1	559.90	559.90
5.	Rear tailgate / DD	1	2,189.30	2,189.30
6.	Rear tailgate w/strip ? - APC	1	391.20	391.20
7.	Outer end panel ?	1	635.25	635.25
8.	Rear RH taillamp X	1	210.40	210.40
9.	Rear windscreen X	1	1,565.30	1,565.30
10.	Exhaust tip X	1	455.00	455.00
11.	70 KM/H sticker / APC	1	15.00	15.00
12.	Hiace emblem / APC	1	75.00	75.00
13.	Toyota emblem / APC	1	65.00	65.00
14.	GL emblem / APC	1	95.00	95.00
15.	Pull to open sticker X	1	15.00	15.00

16.	Emergency door sticker / HCC	1	15.00	15.00
17.	Transfer rear tailgate fittings	1	150.00	50 150.00
18.	Remove & refit rear windscreen to assist repair	1	200.00	170 200.00
19.	Sealant	2	40.00	40 80.00
20.	Check wiring	1	20.00	20.00 ✓
21.	Spray painting with company name	1	1,000.00	600 1,000.00
22.	Labour charges	1	1,200.00	900 1,200.00
SUB-TOTAL				SS9,589.05

- Price before 7% gst

Thank you.

Yours faithfully,

Winnie Chai

Winnie Chai
HP: 9850-9666



Steve (LKK)
27/9/21, 1230L

WIL AL
L/S
My AL My
5 d/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: