

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21009957/R1uce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 21/10/2021 SINGAPORE 068811 ATTN: ANG YVONNE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHC 1135C GBF 7871B Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03I96 Excess (\$) 0.00 ANG YVONNE **Assign Date** 24/09/2021 Assign From **Vehicle Particulars & Condition** 2. TOYOTA HIACE DX 3.0A Make & Model 2982 C.C HIDDEN 2017 Engine No. Year of Reg. KDH2015023693 **GREY** Chassis No. Colour Odometer 237449 KM Steering **IN ORDER IN ORDER** NIL **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195 R15C YOKOHAMA 6 mm YOKOHAMA L/H Front Tyre 195 R15C 6 mm 195 R15C YOKOHAMA R/H Rear Tyre 6 mm YOKOHAMA L/H Rear Tyre 195 R15C 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. 5. **General Information** 17/09/2021 13/10/2021 (01:56 PM) Inspect Date / Time Accident Date ANN JOO MOTOR PL Survey held at BLK 176 SIN MING DRIVE #02-17 SIN MING AUTOCARE SINGAPORE 575721 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM21009957/R1uce2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

RECO Auto Computer CAE Linear Administra

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

3 Working Days