

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/GRB21009958/RGS3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
<b>Claimant Vehicle No :</b>	SDP9888P	<b>Insured Vehicle No :</b>	SLM386B
Date of Loss:	09/09/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003979

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SDP9888P</b>	Engine No:	36635981B38A15A
Make & Model:	BMW 216I, 1.5 D GT LED (A)	Chassis No:	WBA6V120305R45474
Reg. Date:	25/08/2020 (Man. Year: 2020)	Odometer:	27277 km
Colour:	Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	265/55
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,870.50	2,512.60	2,357.90	48.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,125.00	5,127.00	998.00	16.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,995.50</b>	<b>7,639.60</b>	<b>3,355.90</b>	<b>30.52</b>
<b>+ GST 7.00/7.00% (S\$)</b>	769.69	534.77	234.92	30.52
<b>Nett Amount (S\$)</b>	<b>11,765.19</b>	<b>8,174.37</b>	<b>3,590.82</b>	<b>30.52</b>
<b>+ Car Rental (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>8,681.82</b>		

INSPECTION

Date of Assignment:	27/09/2021	
Date Inspected:	27/09/2021 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	5.0 days	

**Adjuster:** MOHD RASUL**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 24 Jan 2022)
<b>Parts:</b> M1-MPV	BMW 216I 1.5 D GT LED (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDP9888P)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS	
2	1		*BOOTLID	Bent	1,216.40 FS	*1,216.40 FS	
3	1		*RR BUMPER LH SIDE GUIDE	Serviceable	161.15 FS	*- FS	
4	1		*REAR BUMPER CARRIER	Serviceable	483.40 FS	*- FS	
5	1		*RR BUMPER LH INNER SIDE GUID	Serviceable	161.15 FS	*- FS	
6	1		*REAR BUMPER TRIM STRIP (BLAC)	Serviceable	72.20 FS	*- FS	
7	1		*REAR BUMPER PANEL PRIMED (L)	Deformed	1,050.65 FS	*1,050.65 FS	
8	1		*LETTERING 216	Not Necessary	64.75 FS	*- FS	
9	2		*GROMMET	Not Necessary	1.60 FS	*- FS	
10	1		*PLAQUE 74MM	Not Necessary	71.95 FS	*- FS	
11	1		*REAR WINDOW (ESG)	Not Necessary	657.60 FS	*- FS	
12	6		*HOOK AND LOOP FASTENER	Not Necessary	13.20 FS	*- FS	
13	1		*REAR LH REFLECTOR	Not Necessary	39.05 FS	*- FS	
14	1		*REAR LH LIGHT IN THE SIDE PANEL	Not Necessary	376.30 FS	*- FS	
15	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS	
16	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Not Necessary	27.85 FS	*- FS	
17	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) (2 PCS)	Necessary	263.10 FS	*131.55 FS	
18	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS	
19	10		*BUMP STOP	Necessary	32.00 FS	*32.00 FS	
					<b>Total Parts (S\$)</b>	<b>4,870.50</b>	<b>2,512.60</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER ,BOOT LID INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	2,550.00	1,700.00
2	TO RESPRAY REAR BUMPER AND BOOT LID	New	1,923.00	1,826.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
4	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR	New	574.00	574.00
5	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
6	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECK ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	504.00
7	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
8	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
			<b>Gross Labour Cost (S\$)</b>	<b>5,127.00</b>
				<b>6,125.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >