

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009962/KRS3Q2
Date: 07/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900249139
Claimant Vehicle No :	SMK6940K	Insured Vehicle No :	SFE4333R
Date of Loss:	22/09/2021	Nature of Claim:	TP
		Claim No:	6752986866SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK6940K	Engine No:	CDN084224
Make & Model:	AUDI A5, 2.0 L TFSI QUATTRO (A)	Chassis No:	WAUZZZ8T5AA032550
Reg. Date:	07/01/2010 (Man. Year: 2009)	Odometer:	83439 km
Colour:	Matt Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,516.25	6,037.11	10,479.14	63.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,790.00	970.00	1,820.00	65.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,306.25	7,007.11	12,299.14	63.71
Approved Total (Overridden) (S\$)		5,600.00		

	(S\$)	19,306.25	5,600.00	13,706.25	70.99
+ GST 7.00/7.00% (S\$)		1,351.44	392.00	959.44	70.99
Nett Amount (S\$)		20,657.69	5,992.00	14,665.69	70.99
	+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
	+ Doc/Search Fee (S\$)		2.00		
	Nett Liability (S\$)		6,494.00		

INSPECTION

Date of Assignment: 24/09/2021

Date Inspected: 04/10/2021

Inspected At: Ding Auto Pte Ltd (HQ)
176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Buckled / Dented	2,000.33 FL	*1,795.00 FL
2	1		*BUMPER DAMPER	Serviceable	200.85 FL	*- FL
3	1		*BUMPER REINF SUPPORT	Repair	999.55 FL	*- FL
4	1		*BUMPER SIDE AIR GUIDE RH	Serviceable	133.75 FL	*- FL
5	1		*BUMPER LOWER TRIM COVER	Repair	400.77 FL	*- FL
6	1		*BUMPER JET WASH ASSY & COVER RH	Serviceable	500.55 FL	*- FL
7	1		*BUMPER RETAINER RH	Distorted	80.17 FL	*80.17 FL
8	1		*BUMPER PARKING SENSOR ASSY RH	Serviceable	251.75 FL	*- FL
9	1		*CENTRE GUIDE BASE +CH TRIM +BADGE	Serviceable	1,400.75 FL	*- FL
10	1		*FRT TOP SUPPORT PANEL +GARNISH	Cracked	1,600.22 FL	*280.00 FL
11	1		*FRT FENDER RH	Buckled	1,111.22 FL	*1,085.00 FL
12	1		*FENDER INNER SHIELD COVER RH	Serviceable	388.75 FL	*- FL
13	1		*HEADLAMP ASSY RH	Cracked	2,500.33 FL	*2,041.00 FL
14	1		*HEADLAMP MODULE CPL RH	Serviceable	1,009.75 FL	*- FL
15	1		*FRT ALLOY RIM RH	Serviceable	2,333.10 FL	*- FL
16	1		*STICKER WRAPPING FRT BUMPER AND FENDER RH	Necessary	1,500.00 FS	*900.00 FS
17	1		*PARKING SENSOR ASSY RH	Serviceable	280.00 FS	*- FS
18	1		*FRT BUMPER AND FENDER CLIPS	Necessary	120.00 FS	*120.00 FS
19	1		*HEADLAMP ECU REPROGRAMMING	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	17,261.84	6,301.17
- List Item Discount on L Items 5.00/5.00% (S\$)	745.59	264.06
Total Parts (S\$)	16,516.25	6,037.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT FRT BUMPER FENDER RH AND BONNET (INNER/OUTER)	New	1,500.00	500.00
2	PANEL BEATING AND STRAIGHTEN ACCIDENT AREA	New	800.00	400.00
3	REMOVE AND INSTALL FRT BUMPER COMPONENTS	New	250.00	50.00
4	ALIGN HEADLAMP AND TEST WIRING	New	120.00	20.00
5	ALIGN REVERSE SENSOR AND TEST WIRING	New	120.00	0.00
			Gross Labour Cost (S\$)	2,790.00
				970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >