

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21009965/UGS3Q2**Date:** 07/02/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MCV0002318_02

Claimant Vehicle No : GBD8414S **Insured Vehicle No :** GBG7109P

Date of Loss: 23/09/2021 Nature of Claim: TP Claim No: MCV2021D0004149

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD8414S**

Make & Model: NISSAN NV200, 1.5 (A) Engine No: K9KC400D054479

Reg. Date: 15/06/2015 (Man. Year: 2015) Chassis No: VSKYBAM20Z0097266

Colour: Grey Odometer: 92670 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,324.90	5,171.35	1,153.55	18.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,210.00	2,630.00	1,580.00	37.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,534.90	7,801.35	2,733.55	25.95
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	10,534.90	7,000.00	3,534.90	33.55
+ GST 7.00/7.00% (S\$)	737.44	490.00	247.44	33.55
Nett Amount (S\$)	11,272.34	7,490.00	3,782.34	33.55
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
Nett Liability (S\$)		8,090.00		
Global Sum Settlement (S\$)		8,050.00		

INSPECTION

Date of Assignment: 24/09/2021

Date Inspected: 24/09/2021 Inspected At: Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Oct 2021)	
Parts:	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD8414S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FLOOR PANEL (NPA)	Repair	0.00 FN	*- FN
2	1		*LH WIPER ARM	Not Necessary	107.30 FN	*- FN
3	1		*NUMBER PLATE LAMP GARNISH	Torn	352.00 FN	*352.00 FN
4	1		*REAR BUMPER	Distorted	485.90 FN	*485.90 FN
5	1		*REAR BUMPER SPONGE	Torn	94.00 FN	*94.00 FN
6	2		*REAR DOOR HINGE	Not Necessary	162.60 FN	*- FN
7	1		*REAR END PANEL INNER	Badly Dented	697.00 FN	*697.00 FN
8	1		*REAR END PANEL TOP GARNISH	Twisted	83.30 FN	*83.30 FN
9	1		*REAR LH DOOR	Badly Dented	1,469.50 FN	*1,469.50 FN
10	1		*REAR LH DOOR CATCH	Not Necessary	34.80 FN	*- FN
11	1		*REAR LH DOOR LOCK	Not Necessary	115.50 FN	*- FN
12	1		*REAR LH DOOR RUBBER	Twisted	88.40 FN	*88.40 FN
13	1		*REAR NISSAN NV200	Necessary	141.70 FN	*141.70 FN
14	1		*REAR NISSAN LOGO	Necessary	157.20 FN	*157.20 FN
15	1		*REAR RH DOOR	Badly Dented	1,102.20 FN	*1,102.20 FN
16	1		*REAR RH DOOR CATCH	Not Necessary	34.80 FN	*- FN
17	1		*REAR DOOR DGI STICKER	Necessary	136.00 FN	*136.00 FN
18	1		*REAR RH DOOR LOCK	Not Necessary	115.80 FN	*- FN
19	1		*REAR RH DOOR RUBBER	Torn	72.60 FN	*72.60 FN
20	1		*REAR RH LAMP	O/S Cracked	619.60 FN	*309.80 FN
21	1		*REAR BUMPER REFLECTOR	O/S Broken	123.80 FN	*61.90 FN
22	1		*REAR END PANEL OUTER	Badly Dented	135.00 FS	*135.00 FS
23	1		*REAR WIPER MOTOR	Not Necessary	212.20 FS	*- FS
24	1		*LH WIPER ARM CAP	Not Necessary	13.10 FS	*- FS
25	1		*REAR 70KM/H	Necessary	15.00 FS	*10.00 FS
26	1		*REAR DOOR 5 PAX	Necessary	15.00 FS	*10.00 FS
27	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
28	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
29	2		*SET REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	6,944.30	5,696.50
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	619.40	525.15
Total Parts (\$\$)	6,324.90	5,171.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER DOOR FITTING	New	320.00	120.00
2	REMOVE AND REFIX REVERSE SENSOR	New	80.00	50.00
3	REMOVE & REFIT REAR WINDSCREEN	New	240.00	200.00
4	SPRAY PAINTING	New	1,750.00	950.00
5	LABOUR CHARGE	New	1,650.00	1,200.00
6	WIRING CHECK	New	50.00	20.00
7	TUFFCOAT	New	120.00	90.00
Gross Labour Cost (\$\$)			4,210.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >