



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 2911S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER FOR BUMPER PRIMED (SN)	TO REPAIR SEE LABOUR	1,313.60	-
1	SUPPORT PARTS BUMPER INNER BRACKET LH (SN)	NOT NECESSARY	59.04	-
1	GUIDE PIECE BUMPER SIDE BRACKET LH (SN)	BROKEN	22.75	22.75
1	GUIDE PIECE BUMPER SIDE BRACKET RH (SN)	NOT NECESSARY	22.75	-
1	GUIDE BUMPER CTR BRACKET (SN)	NOT NECESSARY	42.80	-
1	COOLING AIR GRILL SATIN B BUMPER CTR LOWER GRILLE (SN)	CUT	149.05	149.05
1	COOLING AIR GRILL SATIN B LHS LOWER GRILLE (UPPER) (SN)	CUT	80.01	80.01
1	COVER PART FOR BUMPER SAT LHS LOWER GRILLE (CTR) (SN)	NOT NECESSARY	36.47	-
1	COOLING AIR GRILL SATIN B LHS LOWER GRILLE (LOWER) (SN)	NOT NECESSARY	80.01	-
			1,806.48	251.81
	<u>LABOUR</u>			
	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR.	NOT NECESSARY	280.00	-
	B&P DIAGNOSIS AND PROGRAMMING.		480.00	480.00
	LABOUR. INCLUSIVE OF THE REPAIR OF COVER FOR BUMPER PRIMED.		1,680.00	1,260.00
	SPRAY PAINT.		1,600.00	800.00
			4,040.00	2,540.00
	GRAND TOTAL		5,846.48	2,791.81
	RECOMMENDED COST OF REPAIRS			2,791.81

Report Ref No. CS/GAI21009966/Euf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.