

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21009968/UPA3Q2**Date:** 02/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100188868
<b>Claimant Vehicle No :</b>	SMV3600D	<b>Insured Vehicle No :</b>	SDG7999M
Date of Loss:	23/09/2021	Nature of Claim:	TP
		Claim No:	3074072558SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMV3600D</b>		
Make & Model:	MERCEDES-BENZ CLS350, 2.0 COUPE (R19 LED SR) (A)	Engine No:	26492030056274
Reg. Date:	17/12/2018 (Man. Year: 2018)	Chassis No:	WDD2573502A026340
Colour:	Grey	Odometer:	45113 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	275/35 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	22,142.42	13,670.60	8,471.82	38.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	1,350.00	1,010.00	42.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>24,502.42</b>	<b>15,020.60</b>	<b>9,481.82</b>	<b>38.70</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>12,000.00</b>		
<b>(\$\$)</b>	24,502.42	12,000.00	12,502.42	51.03
<b>+ GST 7.00/7.00% (\$\$)</b>	1,715.17	840.00	875.17	51.03
<b>Nett Amount (\$\$)</b>	<b>26,217.59</b>	<b>12,840.00</b>	<b>13,377.59</b>	<b>51.03</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (\$\$)</b>		500.00		
<b>(\$\$)</b>		13,340.00		
<b>Liabe Amount (80.00%) (\$\$)</b>		<b>10,672.00</b>		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>10,674.00</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>10,500.00</b>		

INSPECTION

Date of Assignment: 24/09/2021

Date Inspected: 24/09/2021 Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay  
Singapore 417883

Estimated Period of Repair: 4.0 days

---

**Adjuster:**    MARCUS CHUA

**Manager:**    CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut /Torn	2,850.00 F	*2,303.15 FL
2	1		*FRONT BUMPER CENTRE LOWER CHROME MOULDING	Not Necessary	355.00 F	*- FL
3	1		*FRONT BUMPER LOGO	Necessary	105.00 F	*90.00 FL
4	1		*FRONT BUMPER PDC SENSOR N/S	Shorted	265.00 F	*185.75 FL
5	1		*FRONT BUMPER BEAM	Not Necessary	815.00 F	*- FL
6	1		*FRONT BUMPER SIDE RETAINER N/S	Not Necessary	108.00 F	*- FL
7	1		*SET FRONT BUMPER CLIPS & RIVET	Necessary	60.00 F	*60.00 FL
8	1		*HEADLAMP MULTI BEAM LED ASSY N/S	Scratched / Cracked	9,800.00 F	*6,946.58 FL
9	1		*FRONT FENDER N/S	Dented/ Bent	1,599.00 F	*1,496.66 FL
10	1		*FRONT FENDER INNER SHIELD N/S	Not Necessary	365.00 F	*- FL
11	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Not Necessary	60.00 F	*- FL
12	1		*FRONT SPORT RIM 19 INCH N/S	Cut / Bent	1,800.00 F	*1,200.00 FL
13	1		*FRONT KNUCKLE ARM N/S	Bent	1,815.42 F	*1,659.44 FL
14	1		*FRONT KNUCKLE ARM BEARING N/S	Damaged	680.00 F	*559.67 FL
15	1		*FRONT LOWER ARM N/S	Bent / Twisted	845.00 F	*688.31 FL
16	1		*FRONT TORSION ARM N/S	Serviceable	620.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	22,142.42	15,189.56
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	1,518.96
Total Parts (S\$)	22,142.42	13,670.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED FRONT PDC SENSOR	New	80.00	50.00
3	TO SPRAY RUST PROOFING	New	100.00	30.00
4	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	280.00	150.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	100.00
6	TO RESET & REPROGRAMME SYSTEM	New	100.00	50.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	800.00	450.00
8	TO PUTTY & SPRAY PAINTING	New	800.00	500.00
<b>Gross Labour Cost (\$)</b>			<b>2,360.00</b>	<b>1,350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >