

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009969/UVCN2**Date:** 04/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00128712100		
Claimant Vehicle No :	SML438D	Insured Vehicle No :	SDE13P		
Date of Loss:	19/09/2021	Nature of Claim:	TP	Claim No:	SNM21D205369

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML438D		Engine No:	L15B5560335
Make & Model:	HONDA VEZEL, 1.5 1.5X CVT (A)		Chassis No:	RU11310324
Reg. Date:	02/05/2019 (Man. Year: 2018)		Odometer:	32178 km
Colour:	Brown			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,866.40	3,036.48	10,829.92	78.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,990.00	1,790.00	2,200.00	55.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,856.40	4,826.48	13,029.92	72.97
Approved Total (Overridden) (\$\$)		3,850.00		
Nett Amount (\$\$)	17,856.40	3,850.00	14,006.40	78.44

INSPECTION

Date of Assignment:	24/09/2021		
Date Inspected:	27/09/2021	Inspected At:	SYNERGY BUILDING KAKI BUKIT #01-44 REPAIRER: TSL AUTO GARAGE
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML438D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Dented/Deformed	1,098.00 FL	*566.20 FL
2	1		*REAR BUMPER LEFT SIDE	Not Necessary	235.00 FL	*- FL
3	1		*REAR BUMPER RIGHT SIDE	Not Necessary	235.00 FL	*- FL
4	1		*REAR BUMPER REFLECTORS	N/s Cracked	368.00 FL	*151.00 FL
5	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	92.00 FL	*- FL
6	1		*REAR LEFT TAILLAMP ASSY	Not Necessary	866.00 FL	*- FL
7	1		*REAR RIGHT TAILLAMP ASSY	Not Necessary	866.00 FL	*- FL
8	1		*REAR TAILGATE ASSY	Dented/Bent	1,887.00 FL	*953.00 FL
9	1		*REAR TAILGATE LEFT TAILLAMP	Not Necessary	342.00 FL	*- FL
10	1		*REAR TAILGATE RIGHT TAILLAMP	Not Necessary	342.00 FL	*- FL
11	1		*REAR TAILGATE INNER LOCK	Bent	210.00 FL	*148.00 FL
12	1		*REAR TAILGATE LOCK SENSOR	Cracked	132.00 FL	*60.80 FL
13	1		*REAR TAILGATE WEATHERSTRIP	Twisted	185.00 FL	*182.60 FL
14	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	385.00 FL	*- FL
15	1		*REAR TAILGATE CENTRE LOGO	Not Necessary	35.00 FL	*- FL
16	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	68.00 FL	*68.00 FL
17	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	Necessary	188.00 FL	*121.30 FL
18	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	212.00 FL	*- FL
19	1		*REAR TAILGATE OUTER GARNISH CHROME MOULDING	Not Necessary	108.00 FL	*- FL
20	2		*REAR TAILGATE NUMBER PLATE LAMPS	Not Necessary	96.00 FL	*- FL
21	2		*REAR TAILGATE HINGES	Not Necessary	144.00 FL	*- FL
22	2		*REAR TAILGATE DAMPERS	Not Necessary	336.00 FL	*- FL
23	1		*REAR TAILGATE INNER PULL POCKET	Not Necessary	67.00 FL	*- FL
24	1		*REAR END PANEL	Dented	630.00 FL	*514.00 FL
25	1		*REAR END PANEL TOP GARNISH	Twisted	102.00 FL	*102.00 FL
26	1		*REAR LEFT FENDER	Not Necessary	2,098.00 FL	*- FL
27	1		*REAR RIGHT FENDER	Not Necessary	2,098.00 FL	*- FL
28	1		*REAR LEFT FENDER PROTECTOR	Torn	198.00 FL	*188.20 FL
29	1		*REAR RIGHT FENDER PROTECTOR	Not Necessary	198.00 FL	*- FL
30	1		*REAR LEFT QUARTER GLASS MOULDING	Not Necessary	165.00 FL	*- FL
31	1		*REAR RIGHT QUARTER GLASS MOULDING	Not Necessary	165.00 FL	*- FL
32	1		*SPARE TYRE COVER	Not Necessary	350.00 FL	*- FL
33	1		*REAR BUMPER UNDER COVER	Deformed/Twisted	328.00 FL	*328.00 FL
34	1		*REAR EXHAUST MUFFLER ASSY	Not Necessary	956.00 FL	*- FL
35	2		*REAR EXHAUST MUFFLER MOUNTINGS	Not Necessary	48.00 FL	*- FL
36	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*40.00 FS
37	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
38	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	100.00 FS	*40.00 FS
39	16		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS
40	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
41	1		*REAR NO PLATE WITH GARNISH	Not Necessary	100.00 FS	*- FS
42	1		*REAR END PANEL SEALANT	Necessary	140.00 FS	*50.00 FS
43	4		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
44	1		*REAR LEFT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
45	1		*REAR RIGHT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
46	1		*REAR LEFT QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

10/4/21, 1:00 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR RIGHT QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
48	6		*REAR LEFT FENDER PROTECTOR CLIPS	Not Necessary	40.00 FS	*- FS
49	6		*REAR RIGHT FENDER PROTECTOR CLIPS	Not Necessary	40.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					17,033.00	3,713.10
- List Item Discount on L Items 20.00/20.00% (\$\$)					3,166.60	676.62
Total Parts (\$\$)					13,866.40	3,036.48
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,400.00	600.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,400.00	800.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	20.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	60.00
5	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	120.00	0.00
6	TO REMOVE AND INSTALL REAR FUEL TANK TO FACILITATE THE REPAIR	New	180.00	0.00
7	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	140.00	80.00
8	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	140.00	60.00
9	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	50.00
10	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	120.00
11	TO REMOVE AND INSTALL REAR LEFT QUARTER GLASS	New	80.00	0.00
12	TO REMOVE AND INSTALL REAR RIGHT QUARTER GLASS	New	80.00	0.00
13	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$\$)			3,990.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >