

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009980/AGA3Q2**Date:** 10/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100344295
Claimant Vehicle No :	SJX2342E	Insured Vehicle No :	GBC6758T
Date of Loss:	21/09/2021	Nature of Claim:	TP
		Claim No:	4155030879SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX2342E	Engine No:	1NZY091196
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305165679
Reg. Date:	25/05/2010 (Man. Year: 2010)	Odometer:	129814 km
Colour:	Blue		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,336.35	2,588.02	3,748.33	59.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,400.00	1,560.00	2,840.00	64.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,736.35	4,148.02	6,588.33	61.36
Approved Total (Overridden) (S\$)		3,300.00		
Nett Amount (S\$)	10,736.35	3,300.00	7,436.35	69.26
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		3,689.00		

INSPECTION

Date of Assignment:	24/09/2021	Ace Autolution Pte Ltd (KAKI BUKIT)
Date Inspected:	27/09/2021 Inspected At:	13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre
Estimated Period of Repair:	5.0 days	Singapore 417807

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH & RH	O/S Cracked	1,179.00 FL	*589.50 FL
2	1		*FRONT BONNET	Not Necessary	710.30 FL	*- FL
3	1		*FRONT BUMPER	Distorted	585.20 FL	*585.20 FL
4	1		*FRONT BUMPER SIDE RETAINER LH & RH	O/S Damaged	145.20 FL	*38.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Dented	410.30 FL	*326.00 FL
6	2		*FRONT BUMPER FOG LAMP COVER LH & RH	Not Necessary	190.40 FL	*- FL
7	1		*FRONT BUMPER TOW COVER	Not Necessary	94.30 FL	*- FL
8	1		*FRONT FENDER RH	Distorted	583.10 FL	*583.10 FL
9	1		*FRONT FENDER INNER SHIELD RH	Deformed	137.80 FL	*137.80 FL
10	1		*FRONT FENDER VVT-I EMBLEM	Necessary	89.10 FL	*89.10 FL
11	1		*FRONT WIPER TANK	Deformed	210.00 FL	*210.00 FL
12	1		*FRONT WIPER TANK MOTOR	Not Necessary	322.00 FL	*- FL
13	1		*FRONT SUPPORT PANEL	Repair	845.00 FL	*- FL
14	1		*FRONT KNUCKLE ARM RH	Not Necessary	585.00 FL	*- FL
15	1		*FRONT KNUCKLE ARM BEARING RH	Not Necessary	211.00 FL	*- FL
16	1		*FRONT LOWER ARM RH	Not Necessary	472.10 FL	*- FL
17	1		*HEADLAMP TOP PANEL	Buckled	212.00 FL	*212.00 FL
18	1		*FRONT RIM RH	Cut	550.00 FS	*450.00 FS
19	1		*FRONT TYRE RH	Not Necessary	350.00 FS	*- FS
20	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
21	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	100.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					8,081.80	3,280.70
- List Item Discount on L Items 25.00/25.00% (\$\$)					1,745.45	692.68
Total Parts (\$\$)					6,336.35	2,588.02
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIR AND REPLACE DAMAGED PARTS	New	1,800.00	700.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED	New	1,600.00	700.00
3	TO REMOVE NAD REFIX WIRING AT DAMAGED AREAS	New	100.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	200.00	50.00
5	TO TOP UP COOLANT AND AIR CON GAS	New	120.00	0.00
6	TO CHECK HEADLAMP BEAM	New	120.00	0.00
7	TO REMOVE AND REPLACE UNDERCARRIAGE PART	New	220.00	0.00
8	TO CONDUCT WHEEL ALIGNMENT TEST	New	120.00	80.00
9	TO CONDUCT WATER SEEPAGE TEST	New	120.00	0.00
Gross Labour Cost (\$\$)			4,400.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >