

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21009981/UGA3Q2**Date:** 20/05/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MCV0000467_03

Claimant Vehicle No : GZ2072J **Insured Vehicle No :** GBD6963L

Date of Loss: 22/09/2021 Nature of Claim: TP Claim No: MCV2021D0004234

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GZ2072J**
 Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 5L5625789
 Reg. Date: 20/01/2006 (Man. Year: 2005) Chassis No: JTFUF34Y103011323
 Colour: Orange Odometer: 510053 km
 Engine Capacity: 2986 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185 R14 Rear Tyre Size: 155 R12 (D)
 Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6/6 mm
 Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,739.10	2,267.45	471.65	17.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,140.00	1,270.00	1,870.00	59.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,879.10	3,537.45	2,341.65	39.83
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	5,879.10	2,800.00	3,079.10	52.37
+ GST 7.00/7.00% (S\$)	411.54	196.00	215.54	52.37
Nett Amount (S\$)	6,290.64	2,996.00	3,294.64	52.37
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
Nett Liability (S\$)		3,424.00		
Global Sum Settlement (S\$)		3,400.00		

INSPECTION

Date of Assignment: 24/09/2021

Date Inspected: 30/09/2021 Inspected At: Jin Auto Services Pte Ltd (Defu)

Blk 14 Defu Lane 10, #01-410/412

Singapore 539195

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 15 Mar 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ2072J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,179.10 FL	*1,179.10 FL
2	1		*TAILGATE LOCK LH	Bent	148.30 FL	*148.30 FL
3	1		*TAILLAMP LH	Serviceable	216.20 FL	*- FL
4	1		*TAILLAMP BRACKET LH	Bent	95.80 FL	*95.80 FL
5	1		*NUMBER PLATE LAMP	Not Necessary	78.00 FL	*- FL
6	1		*TIPPER LOCK BRACKET	Bent	62.40 FL	*62.40 FL
7	1		*TIPPER RUBBER STOPPER LH	Cut	39.00 FL	*39.00 FL
8	1		*TIPPER FLOOR PANEL REPAIR (NPA)	Repair	0.00 FL	*- FL
9	1		*TIPPER LH SIDE GATE REPAIR (NPA)	Repair	0.00 FL	*- FL
10	1		*REAR NUMBER PLATE	Bent	35.00 FS	*14.00 FS
11	1		*TIPPER REAR MEMBER	Bent	850.00 FS	*650.00 FS
12	1		*REAR 70/HR STICKER	Necessary	10.00 FS	*10.00 FS
13	1		*REAR ARTWORK	Necessary	480.00 FS	*450.00 FS
					Sub Total (S\$)	3,193.80 2,648.60
					- List Item Discount on L Items 25.00/25.00% (S\$)	454.70 381.15
					Total Parts (S\$)	2,739.10 2,267.45

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE	New	1,450.00	600.00
2	SPRAY PAINT	New	1,520.00	600.00
3	WIRING CHECKING	New	50.00	20.00
4	TUFF KOTE	New	120.00	50.00
Gross Labour Cost (\$\$)			3,140.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >