

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009982/EEA3Q2**Date:** 10/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SJX8181M **Insured Vehicle No :** SLX854J
 Date of Loss: 17/09/2021 Nature of Claim: TP Claim No: MFL2021D0004091

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJX8181M**
 Make & Model: MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A) Engine No: 4A92CP5071
 Reg. Date: 11/07/2017 (Man. Year: 2017) Chassis No: JMYSRCY1AGU006844
 Colour: White Odometer: 86976 km
 Engine Capacity: 1590 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm
 Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,087.30	1,250.30	3,837.00	75.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	860.00	2,540.00	74.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,487.30	2,110.30	6,377.00	75.14
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	8,487.30	1,700.00	6,787.30	79.97
+ GST 7.00/7.00% (S\$)	594.11	119.00	475.11	79.97
Nett Amount (S\$)	9,081.41	1,819.00	7,262.41	79.97
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,126.45		
Global Sum Settlement (S\$)		2,120.00		

INSPECTION

Date of Assignment: 25/09/2021
 Date Inspected: 27/09/2021 Inspected At: Elite AM Pte Ltd (HQ)
 280 Woodlands Industrial Park E5, #01-17 Harvest
 @ Woodlands
 Singapore 757322
 Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 May 2022)

Parts: 143 MITSUBISHI LANCER 1.6 EX AT LED TAIL LAMP (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJX8181M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Not Necessary	693.00 FL	*- FL
2	1		*BOOT LID WEATHERSTRIP	Not Necessary	166.00 FL	*- FL
3	1		*BOOT LID LOCK	Not Necessary	67.00 FL	*- FL
4	1		*BOOT LID LOGO	Not Necessary	47.00 FL	*- FL
5	1		*BOOT LID LAMP (LH & RH)	Not Necessary	1,050.00 FL	*- FL
6	1		*LANCER EMBLEM	Not Necessary	39.00 FL	*- FL
7	1		*MIVEC EMBLEM	Not Necessary	44.00 FL	*- FL
8	1		*C&C STICKER	Not Necessary	41.00 FL	*- FL
9	2		*TAIL LAMP (LH & RH)	Not Necessary	1,050.00 FL	*- FL
10	1		*REAR BUMPER	Dented	815.00 FL	*815.00 FL
11	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
12	2		*REAR BUMPER RETAINER (LH & RH)	Broken	40.00 FL	*40.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	210.00 FL	*210.00 FL
14	1		*REAR BUMPER REFLECTOR (LH & RH)	N/S Broken	44.00 FL	*22.00 FL
15	1		*TOWING CAP	Not Necessary	20.00 FL	*- FL
16	1		*END PANEL	Repair	506.00 FL	*- FL
17	1		*END PANEL UPPER GARNISH	Not Necessary	150.00 FL	*- FL
18	1		*SPARE TYRE TANK BOARD	Not Necessary	165.00 FL	*- FL
19	1		*SET REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
20	1		*SET REAR NUMBER PLATE WITH HOLDER	Bent	60.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,607.00	1,362.00
- List Item Discount on L Items 10.00/10.00% (S\$)	519.70	111.70
Total Parts (S\$)	5,087.30	1,250.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS TO CUT & WELD WHERE NECESSARY TO REPLACE DAMAGED PARTS AS LISTED ABOVE	New	1,500.00	400.00
2	TO SPRAY PAINTING ON BOOT LID (INNER & OUTER) ,REAR BUMPER ,REAR END PANEL	New	1,200.00	400.00
3	TO REMOVE & REPLACE REVERSE SENSORS & TEST FUNCTION	New	120.00	30.00
4	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS	New	280.00	0.00
5	TO REMOVE & TRANSFER BOOT LID SERVICEABLE COMPONENTS & TRIMMINGS TO BOOT LID & TEST FUNCTION	New	150.00	0.00
6	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS	New	150.00	30.00
Gross Labour Cost (\$\$)			3,400.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >