1/28/22, 1:19 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21009992/KVCN2

28/01/2022 Date:

**REFERENCE** 

No:

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00123412000

**Claimant Vehicle** 

SMV4089Z

No:

Insured Vehicle GBK8240P

Date of Loss: 23/09/2021

Nature of Claim: TP

Claim

No:

SNM21D205434/C2/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SMV4089Z Reg No:

Make & Model: TOYOTA NOAH, 1.8 (A) Engine No: 2ZR2G41527 Reg. Date: 29/09/2020 (Man. Year: 2019) Chassis No: ZWR800428408 Colour: Purple Odometer: 54651 km

**Engine Capacity:** 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17 Front Left Side: Rear Left Side: Goodvear 8 mm Goodvear 8 mm Front Right Side: Goodyear 8 mm Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,542.52	1,019.65	1,522.87	59.90
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,380.00	1,430.00	950.00	39.92
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,922.52	2,449.65	2,472.87	50.24
	Approved Total (Overridden) (S\$)		1,950.00		
	Nett Amount (S\$)	4.922.52	1.950.00	2.972.52	60.39

**INSPECTION** 

Date of Assignment: 24/09/2021

Lim Yew Boo Spray Paint Co (HQ) Date Inspected: 28/09/2021 Inspected At:

Blk 10 Sin Ming Industrial Estate, #01-10

Singapore 575645

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jan 2022)

Parts: M1-MPV TOYOTA NOAH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMV4089Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

	Condition	Repairer's	Amount
ER/RH	Bent	1,052.20 FL	*1,052.20 FL
ER INNER SHIELD CLIP/RH	Not Necessary	44.00 FL	*- FL
R/RH	Repair	1,672.30 FL	*- FL
R OUTER CHANNEL/RH	Serviceable	105.70 FL	*- FL
R FRAME STICKER	Not Necessary	208.50 FL	*- FL
ER EMBLEM	Necessary	102.50 FS	*102.50 FS
MIRROR COVER/RH	Dented	128.00 FS	*128.00 FS
	Sub Total (S\$)	3,313.20	1,282.70
- List Item Discount on L Items 25.00/25.00% (S\$)			263.05
	Total Parts (S\$)	2,542.52	1,019.65
	Poport was unsubmitted du	Total Parts (S\$)  Report was unsubmitted during this print-out.	

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\_printrpt&caseid=1035192&extid=370574&CFID=91551...

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS	New	120.00	30.00
2	TO TRANSFER FRONT DOOR MECHANISM TO NEW DOOR	New	80.00	0.00
3	TO CHECK WATER SEEPAGE	New	60.00	0.00
4	TO COMPUTERISE WHEEL ALIGNMENT	New	120.00	0.00
5	LABOUR TO REPLACE & SUPPLY THE WRAPPING ON FRT DOOR,FRT FENDER & LOWER SIDE SKIRT	New	600.00	400.00
6	TO REPAIR, PANEL BEAT, RE-ALIGN & LABOUR TO REPLACE ABOVE PARTS	New	600.00	400.00
7	TO SPRAY PAINT ON RH-FRT FENDER, DOOR & LOWER SIDE SKIRT	New	800.00	600.00
	Gross Labour Cost (S\$)		2,380.00	1,430.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >