

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21009994/TQCE2

Date: 20/09/2022

REFERENCE

Insured/Claimant: HARI JAYA SINGH KIRAN KUMAR Policy No: 1700058585-03
Date of Loss: 21/09/2021 Nature of Claim: OD Claim No: 0142998847SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS6931G**
Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZ531220
Reg. Date: 30/09/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V5J1013790
Colour: Red Odometer: 76785 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$79,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,838.00	4,546.00	1,292.00	22.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,922.00	2,572.00	3,350.00	56.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,760.00	7,118.00	4,642.00	39.47
+ GST 7.00/7.00% (S\$)	823.20	498.26	324.94	39.47
Nett Amount (S\$)	12,583.20	7,616.26	4,966.94	39.47

INSPECTION

Date of Assignment: 27/09/2021

Date Inspected: 24/09/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$913.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Bent	3,039.00 FS	*3,039.00 FS
2	1		*REAR DOOR OUTER SEAL - LH	Necessary	161.00 FS	*161.00 FS
3	1		*BONDING AGENT	* Check	49.00 FS	*- FS
4	1		*CLEANING SOLUTION	* Check	68.00 FS	*- FS
5	1		*APPLICATOR	* Check	8.00 FS	*- FS
6	1		*REAR DOOR ATTACHMENT PARTS - LH	Not Necessary	129.00 FS	*- FS
7	1		*REAR DOOR CATCH	* Check	94.00 FS	*- FS
8	1		*REAR WHEEL SPOILER - LH REAR	* Check	65.00 FS	*- FS
9	1		*REAR WHEEL HOUSING LINER - LH	* Check	240.00 FS	*- FS
10	1		*REAR WHEEL HOUSING LINER ATTACHMENT PART - LH	* Check	89.00 FS	*- FS
11	1		*REAR ALUMINIUM RIM - LH	Cut	1,166.00 FS	*1,166.00 FS
12	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
13	1		*REAR TYRE - LH	Not Necessary	250.00 FS	*- FS
14	1		*SUNDRIES	* Check	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	5,838.00	4,546.00
-------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPEFT FOR DAMAGES	New	350.00	350.00
2	TO DISMANTLE AND RENEW LHS REAR DOOR. TO REPAIR LHS REAR FENDER AND LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS	New	2,100.00	100.00
3	TO RESPRAY LHS REAR DOOR, LHS REAR FENDER AND LHS SILL PANEL	New	3,000.00	1,650.00
4	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			5,922.00	2,572.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >