

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21009995/TTCN2**Date:** 13/05/2022**REFERENCE**

Insured/Claimant:	BOYD LARA MEREDITH	Policy No:	1800136280-02	
Date of Loss:	20/09/2021	Nature of Claim:	OD	Claim No: 1375721361SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMF7304S</b>		
Make & Model:	AUDI Q2 SPORT, 1.4 TFSI COD S-TRONIC (A)	Engine No:	CZE844710
Reg. Date:	22/11/2008 (Man. Year: 2008)	Chassis No:	WAUZZZGA0KA010814
Colour:	Black	Odometer:	15459 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$110,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,563.00	2,767.68	4,795.32	63.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,072.00	2,572.00	6,500.00	71.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,635.00</b>	<b>5,339.68</b>	<b>11,295.32</b>	<b>67.90</b>
<b>- Excess (S\$)</b>	800.00	800.00	0.00	0.00
<b>(S\$)</b>	15,835.00	4,539.68	11,295.32	71.33
<b>+ GST 7.00/7.00% (S\$)</b>	1,108.45	317.78	790.67	71.33
<b>Nett Amount (S\$)</b>	<b>16,943.45</b>	<b>4,857.46</b>	<b>12,085.99</b>	<b>71.33</b>

**INSPECTION**

Date of Assignment:	27/09/2021		
Date Inspected:	24/09/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER-LH	Not Necessary	1,147.00 FS	*- FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	40.00 FS	*- FS
3	1		*FRONT FENDER BRACKET-LH	Not Necessary	16.00 FS	*- FS
4	2		*FRONT WHEEL ARCH COVER-LH/RH	Not Necessary	644.00 FS	*- FS
5	1		*FRONT DOOR-LH	Bent	2,756.00 FS	*2,204.80 FS
6	1		*FRONT DOOR ATTACHMENT PARTS-LH	Not Necessary	94.00 FS	*- FS
7	1		*FRONT DOOR CATCH-LH	Bent	120.00 FS	*96.00 FS
8	1		*FRONT DOOR INNER SEAL-LH	Not Necessary	161.00 FS	*- FS
9	1		*FRONT DOOR COVER-LH	Deformed	257.00 FS	*205.20 FS
10	1		*FRONT POWER WINDOW REGULATOR-LH	Not Necessary	282.00 FS	*- FS
11	1		*FRONT POWER WINDOW REGULATOR MOTOR-LH	Not Necessary	241.00 FS	*- FS
12	1		*FRONT DOOR INNER COVER-LH	Deformed	13.00 FS	*9.84 FS
13	1		*SIDE MEMBER TRIM-LH	Cut	238.00 FS	*190.40 FS
14	1		*FRONT DOOR SEAL OUTER-LH	Necessary	50.00 FS	*47.28 FS
15	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
16	1		*SUNDRIES	Necessary	300.00 FS	*14.16 FS
17	1		*FRONT WING MIRROR MOUNTING-LH	Not Necessary	1,024.00 FS	*- FS
					<b>Total Parts (S\$)</b>	<b>7,563.00      2,767.68</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	400.00	280.00
3	TO DISMANTLE AND REINSTALL FRONT BUMPER.TO RENEW LHS FRONT FENDER AND LHS FRONT DOOR.TO REPAIR LHS SILL PANEL AND DOOR ENTRANCE.RE-ORGANOZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,000.00	1,000.00
4	TO RESPRAY LHS FRONT FENDER,LHS FRONT DOOR,LHS SILL PANEL,LHS WING MIRROR COVER AND DOOR ENTRANCE	New	4,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$)</b>			<b>9,072.00</b>	<b>2,572.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >