

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21009999/UPA3Q2**Date:** 24/03/2023**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SLV4111D**Insured Vehicle No :** SJY123D

Date of Loss: 06/03/2021

Nature of Claim: TP

Claim No: 9133199455SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLV4111D**

Make &amp; Model: TOYOTA VOXY HYBRID, 1.8 (A)

Engine No: 2ZR8245805

Reg. Date: 28/12/2017 (Man. Year: 2017)

Chassis No: ZWR800283931

Colour: White

Odometer: 364522 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: KAPSEN 6 mm

Rear Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side: KAPSEN 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	25.00	0.00	25.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	550.00	1,050.00	65.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>1,625.00</b>	<b>550.00</b>	<b>1,075.00</b>	<b>66.15</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment: 27/09/2021

Date Inspected: 29/09/2021

Inspected At:

Allswell Motor Traders (HQ)

25 Defu Lane 9

Singapore 539266

Estimated Period of Repair: 2.0 days

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CLIPS /RETAINER	Not Necessary	25.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$)					25.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL KNOCKING & REALIGN OF LH SLIDING DOOR	New	1,000.00	150.00
2	SPRAY PAINTING X2 DOOR (PUTTY /POLISH/GUIND/WASH)	New	600.00	400.00
<b>Gross Labour Cost (S\$)</b>			<b>1,600.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >