

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010000/KUCE2

Date: 26/11/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00034622103		
Claimant Vehicle No :	SLM6761L	Insured Vehicle No :	GBH2682C		
Date of Loss:	23/09/2021	Nature of Claim:	TP	Claim No:	SNM21D205433

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM6761L	Engine No:	PY20941781
Make & Model:	MAZDA 6, 2.5 SEDAN SP.6EAT SR LED (A)	Chassis No:	JM6GL1031H0120220
Reg. Date:	05/04/2017 (Man. Year: 2017)	Odometer:	104712 km
Colour:	Metallic Black		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45Z R19	Rear Tyre Size:	225/45Z R19
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,317.04	6,836.56	8,480.48	55.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,190.00	1,260.00	1,930.00	60.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,507.04	8,096.56	10,410.48	56.25
Approved Total (Overridden) (\$\$)		6,400.00		
(\$\$)	18,507.04	6,400.00	12,107.04	65.42
+ GST 7.00/7.00% (\$\$)	1,295.49	448.00	847.49	65.42
Nett Amount (\$\$)	19,802.53	6,848.00	12,954.53	65.42

INSPECTION

Date of Assignment:	26/09/2021	
Date Inspected:	27/09/2021 Inspected At:	Esteem Performance Pte Ltd (HQ) 176 Sin Ming Autocare Sin Ming Drive, #01-14 & #01-15 & #01-16 Singapore 575721
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2021)
Parts:	143	MAZDA 6 2.5 SEDAN SP.6EAT SR LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM6761L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,285.00 FL	*- FL
2	1		*BONNET LOCK	Repair	269.00 FL	*- FL
3	1		*BONNET HINGE LH	Repair	67.00 FL	*- FL
4	1		*BONNET HINGE RH	Repair	67.00 FL	*- FL
5	1		*HEADLAMP RH	Cracked	4,975.00 FL	*4,975.00 FL
6	1		*FRONT GRILLE	Mtg Cracked	161.00 FL	*161.00 FL
7	1		*FRONT GRILLE LOGO	Necessary	86.00 FL	*86.00 FL
8	1		*FRONT GRILLE CHROME	Cracked	195.00 FL	*195.00 FL
9	1		*FRONT SUPPORT PANEL (COMPLETE)	Serviceable	594.00 FL	*- FL
10	1		*FRONT BUMPER	Bent / Torn	1,312.00 FL	*1,211.90 FL
11	10		*FRONT BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Repair	680.00 FL	*- FL
13	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	35.00 FL	*- FL
14	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	35.00 FL	*35.00 FL
15	1		*FRONT BUMPER BRACKET LH	Repair	48.00 FL	*- FL
16	1		*FRONT BUMPER BRACKET RH	Repair	48.00 FL	*- FL
17	1		*FRONT BUMPER SPONGE	Serviceable	97.00 FL	*- FL
18	1		*FRONT BUMPER CHROME MOULDING RH	Dented	112.00 FL	*112.00 FL
19	1		*FOG LAMP RH	Mtg Cracked	694.00 FL	*694.00 FL
20	1		*FOG LAMP GARNISH RH	Cracked	53.00 FL	*53.00 FL
21	1		*FRONT BUMPER LOWER RUBBER	Serviceable	176.00 FL	*- FL
22	1		*RH FRONT FENDER	Bent	394.00 FL	*394.00 FL
23	1		*RH FRONT FENDER UNDERSHIELD	Distorted	165.00 FL	*165.00 FL
24	10		*RH FRONT FENDER UNDERSHIELD CLIP	Necessary	50.00 FL	*50.00 FL
25	1		*RH FRONT LOWER ARM	Serviceable	554.00 FL	*- FL
26	1		*RH FRONT SHOCK ABSORBER	Serviceable	393.00 FL	*- FL
27	1		*RH FRONT SHOCK ABSORBER TOP MOUNTING	Serviceable	107.00 FL	*- FL
28	1		*RH FRONT SHOCK ABSORBER STOPPER	Serviceable	65.00 FL	*- FL
29	1		*RH FRONT KNUCKLE ARM	Serviceable	448.00 FL	*- FL
30	1		*RH FRONT KNUCKLE BEARING}	Serviceable	597.00 FL	*- FL
31	1		*RH FRONT WHEEL HUB}		-	-
32	1		*RH FRONT WHEEL HUB LOCK NUT	Serviceable	35.00 FL	*- FL
33	1		*RH FRONT TIE ROD	Serviceable	165.00 FL	*- FL
34	1		*RH FRONT TIE ROD END	Serviceable	185.00 FL	*- FL
35	1		*RH FRONT DRIVE SHAFT	Serviceable	2,525.00 FL	*- FL
36	1		*RH FRONT RIM	Serviceable	1,498.00 FL	*- FL
37	1		*RH FRONT TYRE	Serviceable	450.00 FS	*- FS
38	1		*WASHER TANK	Dented	109.80 FL	*109.80 FL
39	1		*FRONT BUMPER SENSOR RH	Dented	254.00 FL	*254.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	19,033.80	8,545.70
- List Item Discount on L Items 20.00/20.00% (S\$)	3,716.76	1,709.14
Total Parts (S\$)	15,317.04	6,836.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, BONNET, SUPPORT PANEL, RHF FENDER, RHF DOOR)	New	1,200.00	500.00
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET, SUPPORT PANEL, RHF FENDER, RHF DOOR)	New	1,000.00	600.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE & REFIT FRONT BUMPER SENSOR	New	120.00	50.00
5	TO TUFF COAT	New	150.00	30.00
6	TO REMOVE & REFIT AIRCON CONDENSOR TO ASSIST WORK LOAD. TO TOP UP A/C GAS	New	150.00	0.00
7	TO REMOVE & REFIT RADIATOR TO ASSIST WORK LOAD	New	150.00	0.00
8	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD	New	250.00	0.00
9	TO DO WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (\$\$)			3,190.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >