

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21010003/GRS3Q2**Date:** 07/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070152618
<b>Claimant Vehicle No :</b>	SHA9144J	<b>Insured Vehicle No :</b>	GBK7327E
Date of Loss:	26/09/2021	Nature of Claim:	TP
		Claim No:	3991542226SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHA9144J</b>	Engine No:	G4LEJU188495
Make & Model:	HYUNDAI AE IONIQ, 1.6 (A)	Chassis No:	KMHC851CVKU140769
Reg. Date:	23/04/2019 (Man. Year: 2018)	Odometer:	421194 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,134.40	257.60	1,876.80	87.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,520.00	890.00	630.00	41.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,654.40</b>	<b>1,147.60</b>	<b>2,506.80</b>	<b>68.60</b>
<b>+ GST 7.00/7.00% (S\$)</b>	255.81	80.33	175.48	68.60
<b>Nett Amount (S\$)</b>	<b>3,910.21</b>	<b>1,227.93</b>	<b>2,682.28</b>	<b>68.60</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment:	27/09/2021	
Date Inspected:	27/09/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

**Adjuster:** XING GUO QIANG**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	*- FL
2	10		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER SIDE BRACKE LH	Not Necessary	55.80 FL	*- FL
4	1		*REAR FENDER LH	Repair	1,768.30 FL	*- FL
5	2		*REAR FENDER ADVERTISEMENT RH/LH	Necessary	200.00 FS	*200.00 FS
6	1		*REAR BUMPER MAT	Not Necessary	50.00 FS	*- FS
7	1		*REAR FENDER (PETROL ONLY) LH	Necessary	40.00 FS	*40.00 FS
					<b>Sub Total (\$\$)</b>	<b>2,595.50</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>461.10</b>
					<b>Total Parts (\$\$)</b>	<b>2,134.40</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	350.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
<b>Gross Labour Cost (S\$)</b>			<b>1,520.00</b>	<b>890.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >