

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21010004/VUF3E2

Date: 08/10/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : GBG5331B **Insured Vehicle No :** SMY4631S
Date of Loss: 25/09/2021 Nature of Claim: TP Claim No: MFL2021D0004176

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG5331B**
Make & Model: NISSAN NV200, 1.5 ABS AIRBAG 2WD 6DR EURO E5 W/RC (M) Engine No: K9KC400D057261
Reg. Date: 29/08/2017 (Man. Year: 2017) Chassis No: VSKYBAM20Z0145916
Colour: Silver Odometer: 168457 km
Engine Capacity: 1461 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 165/70 R14 Rear Tyre Size: 165/70 R14
Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm
Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/09/2021
Date Inspected: 27/09/2021 Inspected At: Alpha Car Services Pte Ltd (HQ)
Estimated Period of Repair: 0.0 days Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay
Singapore 417883

Adjuster: Thevan Thomas Karthikesavan

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 Oct 2021)	
Parts:	N/A	NISSAN NV200 1.5 ABS AIRBAG 2WD 6DR EURO E5 W/RC (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for GBG5331B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >