

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010005/UQC2**Date:** 06/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00125922000

Claimant Vehicle No : SLH1236X **Insured Vehicle No :** YN6427T

Date of Loss: 21/09/2021 Nature of Claim: TP Claim No: SNM21D205402/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH1236X**

Make & Model: VOLVO S60, 1.5 T2 (A) Engine No: B4154T51751349

Reg. Date: 25/10/2016 (Man. Year: 2016) Chassis No: YV1FS28C0H2427175

Colour: Grey Odometer: 86153 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16 Rear Tyre Size: 215/55 R16

Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,438.00	1,714.50	1,723.50	50.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	930.00	420.00	510.00	54.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,368.00	2,134.50	2,233.50	51.13
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	4,368.00	1,700.00	2,668.00	61.08
+ GST 7.00/7.00% (S\$)	305.76	119.00	186.76	61.08
Nett Amount (S\$)	4,673.76	1,819.00	2,854.76	61.08

INSPECTION

Date of Assignment: 27/09/2021

Date Inspected: 30/09/2021 Inspected At: SME Motor Pte Ltd (HQ)
1 KAKI BUKIT AVE6, #02-15
Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Oct 2021)
Parts:	143	VOLVO S60 1.5 T2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH1236X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	2,250.00 FL	*1,845.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	120.00 FL	*60.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	1,450.00 FL	*- FL
					Sub Total (\$\$)	3,820.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	382.00
					Total Parts (\$\$)	3,438.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	LABOUR CHARGE	New	400.00	200.00
3	SPRAY PAINTING	New	500.00	200.00
Gross Labour Cost (\$\$)			930.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >