10/26/21, 1:30 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010006/DUCN2

26/10/2021 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMPCSNW00133542005

Claimant Vehicle

SMQ6265U

Insured Vehicle No:

SKM7348C

TP

No: Date of Loss: 22/09/2021

Nature of Claim:

Claim

Chassis No:

Odometer:

SNM21D205417/C02/TANCHC

KMHD841CMLU011246

15732 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMQ6265U Reg No:

HYUNDAI AD AVANTE, 1.6 GLS S (A) Make & Model:

G4FGKU475154 Engine No:

Reg. Date: 27/11/2019 (Man. Year: 2019) Colour:

Beige

1591 cc

Engine Capacity: Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Rear Left Side: Nexen 5 mm Nexen 5 mm Front Right Side: Nexen 5 mm Rear Right Side: Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	402.64	367.20	35.44	8.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	760.00	760.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,162.64	1,127.20	35.44	3.05
+ GST 7.00/7.00% (S\$)	81.38	78.90	2.48	3.05
Nett Amount (S\$)	1,244.02	1,206.10	37.92	3.05

INSPECTION

Date of Assignment: 27/09/2021

Vin's Auto Pte Ltd (Vin's Auto)

Date Inspected: 29/09/2021 Inspected At: Sin Ming AutoCity,, 160 Sin Ming Drive #03-03

Singapore 575722

Estimated Period of Repair: 2.0 days

Adjuster: **BRYAN TANI** Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Oct 2021)

Parts: 143 HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMQ6265U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	459.00 FL	*459.00 FL
2	1		*REAR BUMPER RH SIDE RETAINER	Serviceable	44.30 FL	*- FL
F=Fra	nchise	part. L=ListIten	nDisc.	_		
				Sub Total (S\$)	503.30	459.00
			- List Item Discount on L	Items 20.00/20.00% (S\$)	100.66	91.80
				Total Parts (S\$)	402.64	367.20
			Report was unsubmitted duri	ng this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REPAIR DAMAGES	New	380.00	380.00
2	TO SPRAY PAINTING	New	380.00	380.00
		Gross Labour Cost (S\$)	760.00	760.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >