

SLF 8388E 2016 July.

TP AXA.

Honda Vezel 1496 cc

Veron.

RU11114719

Front Bumper	torn	880.	✓
Front Bumper Clips.	NE	30(SN)	✓
Front Bumper Side Holder LH.	NE	32	✓
Headlamp LH	cracked	1860.	✓
Headlamp Lower Bracket LH.	NE	78	×
Front LH Fender	Dented	591	✓
Front LH Fender Arc Garnish	cut	185	✓
Front LH Fender Arc Garnish Clips.	NE	20(SN)	✓
Front LH Fender Inner Shield	NE	179	×
Front LH Fender Inner Shield Clips.	NE	30(SN)	+
Bonnet	Dented	992	✓
Bonnet Hinge LH.	xp on	79	×

SLF 8388E.

Front LH Door Regis 988 +

Front LH Door Wing Mirror Durd 952 ✓

Front LH Wheel Rim. NP 800(SN) X
MN

5492

S-V: 50

4393.60

Panel Beating

~~1000~~ 800

Spray Painting

~~1000~~ 900

Wiring.

1810

~~50~~ 30

To spray tuff coat.

~~150~~ 80

To transfer door fittings.

150 X

To perform wheel alignment.

150 X

5240

10,196.00

Total: 6253.60

H/s: SK

05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SK