



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 3547P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	TO REPAIR SEE LABOUR	2,165.00	-
1	BOOTLID REAR LOGO	NECESSARY	69.40	69.40
1	BOOTLID 7 G-TRONIC EMBLEM	NECESSARY	75.00	75.00
1	BOOTLID E 250 EMBLEM	NECESSARY	82.00	82.00
1	BOOTLID C&C LOGO	NECESSARY	50.00	50.00
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	232.20	-
1	REAR BUMPER	DENTED / DEFORMED	1,537.12	1,537.12
1	REAR BUMPER LOWER GARNISH	DISTORTED	288.20	288.20
1	REAR BUMPER CENTRE CHROME MOULDING	SCRATCHED / NECESSARY	232.35	232.35
2	REAR BUMPER SIDE CHROME MOULDINGS @\$161.00	SCRATCHED / NECESSARY	322.00	322.00
1	REAR BUMPER PDC SENSOR	SHORTED	195.00	195.00
1	REAR BUMPER REINFORCEMENT	BENT	545.22	545.22
1	SET REAR BUMPER CLIPS & RIVERT	NECESSARY	60.00	60.00
2	REAR BUMPER SIDE HOLDERS @\$165.00	O/S CRACKED	330.00	165.00
1	REAR BUMPER EXHAUST CHOME O/S	BENT	182.00	182.00
1	REAR BUMPER TOP RETAINER	CRACKED	158.20	158.20
1	REAR END PANEL	TO REPAIR SEE LABOUR	813.70	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	223.50	-
1	TAILLAMP O/S	CRACKED	672.30	672.30
	LESS 10% DISCOUNT		-823.32	-463.38
			7,409.87	4,170.41
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REAR PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-

Report Ref No. CS/TP21010008/Uqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESET & REPROGRAMME SYSTEM.		100.00	80.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID AND REAR END PANEL.		800.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,280.00	1,000.00
			2,580.00	1,830.00
GRAND TOTAL			9,989.87	6,000.41
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,800.00

Report Ref No. CS/TP21010008/Uqf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.