

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21010009/KVF3E2

Date: 07/12/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001750220

Claimant Vehicle No : SKX2020Y

Insured Vehicle No : SML8416P

Date of Loss: 24/09/2021

Nature of Claim: TP

Claim No: 263144

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX2020Y**

Make & Model: TOYOTA PRIUS PLUS, 1.8 (A)

Engine No: 2ZR2H40932

Reg. Date: 15/10/2020 (Man. Year: 2020)

Chassis No: JTDZS3EU60J060650

Colour: Metallic Grey

Odometer: 6377 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Dunlop 9 mm

Rear Left Side: Dunlop 9 mm

Front Right Side: Dunlop 9 mm

Rear Right Side: Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,603.50	4,156.80	446.70	9.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	700.00	950.00	57.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,253.50	4,856.80	1,396.70	22.33
Approved Total (Overridden) (S\$)		3,850.00		
Nett Amount (S\$)	6,253.50	3,850.00	2,403.50	38.43

INSPECTION

Date of Assignment: 27/09/2021

Date Inspected: 04/10/2021 Inspected At:

Blk 1 Sin Ming Industrial Sector C #01-135

Repairer: A T Auto

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2021)
Parts:	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX2020Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	650.00 FL	*556.40 FL
2	1		*FRONT BUMPER GRILLE	Mtg Cracked	520.00 FL	*186.00 FL
3	1		*FRONT BUMPER SPONGE	Serviceable	168.00 FL	*- FL
4	2		*FRONT HEADLAMP	Mtg Cracked	4,800.00 FL	*4,800.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	6,138.00	5,542.40
- List Item Discount on L Items 25.00/25.00% (S\$)	1,534.50	1,385.60
Total Parts (S\$)	4,603.50	4,156.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS }	New	600.00	300.00
2	RE-ALIGNMENT OF FRONT SUPPORT PANEL }	New	300.00	0.00
3	SPRAY PAINTING ON ACCIDENT AREAS	New	600.00	400.00
4	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (\$\$)			1,650.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >