4/6/22, 3:17 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21010010/EGA3Q2

Date: 06/04/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447

Claimant Vehicle SMU8370P Insured Vehicle No : SLM9810J

No:

Date of Loss: 25/09/2021 Nature of Claim: TP Claim No: MFL2021D0004191

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMU8370P

Make & Model:

LAND ROVER DISCOVERY SPORT, 2.0 D 7-SEATER Engine No: 200622Y0269PT204

(180PS) (A) Englie No. 20002210209F1204
Reg. Date: 31/08/2020 (Man. Year: 2020) Chassis No: SALCA2AX2LH870798

 Reg. Date:
 31/08/2020 (Man. Year: 2020)
 Chassis No:
 SALCA2A

 Colour:
 Blue
 Odometer:
 12043 km

Engine Capacity: 1997 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm
Front Right Side: Pirelli 4 mm
Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------------------|------------|------------|------------|--------|
| Parts | | 5,659.50 | 1,314.09 | 4,345.41 | 76.78 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 8,001.00 | 4,651.00 | 3,350.00 | 41.87 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Gross Total (S\$) | 13,660.50 | 5,965.09 | 7,695.41 | 56.33 |
| | + GST 7.00/7.00% (S\$) | 956.24 | 417.56 | 538.68 | 56.33 |
| | Nett Amount (S\$) | 14,616.74 | 6,382.65 | 8,234.09 | 56.33 |
| | | | | | |

+ Car Rental (4.0 x S\$130.00/day + 7.00% GST) (S\$) 556.40

Nett Liability (S\$) 6,939.05

INSPECTION

Date of Assignment: 27/09/2021

Wearnes Automotive Pte Ltd (Leng Kee)
Date Inspected: 25/10/2021 Inspected At: 28 Leng Kee Road

28 Leng Kee Road Singapore 159105

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/6/22, 3:17 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 23 Dec 2021)

Parts: N/A LAND ROVER DISCOVERY SPORT 2.0 D 7-SEATER (180PS) (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SMU8370P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|----------|--|---|--|---|---|
| 1 | | *DOOR PANEL REAR RH D | Repair | 2,670.30 FS | *-FS |
| 1 | | *SEAL -DOOR FRONT AN | Not Necessary | 145.20 FS | *-FS |
| 1 | | *SEAL -DOOR FRONT AN | Not Necessary | 254.40 FS | *-FS |
| 1 | | *MOULDING -DOOR OUTS | Not Necessary | 283.30 FS | *-FS |
| 1 | | *MOULDING -REAR WHEE | Not Necessary | 197.70 FS | *-FS |
| 1 | | *WHEEL -ALLOY | Cut | 1,460.10 FS | *1,314.09 FS |
| 1 | | *SOUND DEADENING PAD | Not Necessary | 578.00 FS | *-FS |
| 15 | | *BUMPER NUT XF | Not Necessary | 70.50 FS | *- FS |
| nchise p | art. S=SpcNe | tt. | | | |
| | | | Total Parts (S\$) | 5,659.50 | 1,314.09 |
| | 1 1 1 1 1 1 1 1 15 | 1 1 1 1 1 1 1 1 1 1 5 | 1 *DOOR PANEL REAR RH D 1 *SEAL -DOOR FRONT AN 1 *SEAL -DOOR FRONT AN 1 *MOULDING -DOOR OUTS 1 *MOULDING -REAR WHEE 1 *WHEEL -ALLOY 1 *SOUND DEADENING PAD | 1 *DOOR PANEL REAR RH D Repair 1 *SEAL -DOOR FRONT AN Not Necessary 1 *SEAL -DOOR FRONT AN Not Necessary 1 *MOULDING -DOOR OUTS Not Necessary 1 *MOULDING -REAR WHEE Not Necessary 1 *WHEEL -ALLOY Cut 1 *SOUND DEADENING PAD Not Necessary 15 *BUMPER NUT XF Not Necessary 15 *BUMPER NUT XF Not Necessary | 1 *DOOR PANEL REAR RH D Repair 2,670.30 FS 1 *SEAL -DOOR FRONT AN Not Necessary 145.20 FS 1 *SEAL -DOOR FRONT AN Not Necessary 254.40 FS 1 *MOULDING -DOOR OUTS Not Necessary 283.30 FS 1 *MOULDING -REAR WHEE Not Necessary 197.70 FS 1 *WHEEL -ALLOY Cut 1,460.10 FS 1 *SOUND DEADENING PAD Not Necessary 578.00 FS 15 *BUMPER NUT XF Not Necessary 70.50 FS nchise part. S=SpcNett. 70.50 FS |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------------|---|---------------|------------|----------|
| <u>Lab</u> | our Items | | | |
| 1 | TO REPLACE REAR RH DOOR ,REPAIR FRT RH DOOR ,ETC | New | 3,000.00 | 1,000.00 |
| 2 | TO SPRAYPAINT ON FRT RH DOOR ,REAR RH DOOR ,ETC | New | 2,700.00 | 2,700.00 |
| 3 | TO REMOVE, REFIT & TRANSFER REAR RH DOOR PARTS | New | 500.00 | 0.00 |
| 4 | TO REPLACE REAR RH TYRE | New | 850.00 | 0.00 |
| 5 | TO REPLACE REAR RH RIM | New | 50.00 | 50.00 |
| 6 | WHEEL ALIGNMENT | New | 280.00 | 280.00 |
| 7 | TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES | New | 621.00 | 621.00 |
| | Gross Labour Cost (S\$) | | 8,001.00 | 4,651.00 |
| | Report was unsubmitted during th | is print-out. | | |

< END OF ESTIMATES >