

# PERFECT AUTOMOBILE APPRAISAL SERVICES

10 Hougang Street 11 #14-29 The Minton Singapore 534080

Hand phone No. 96683949

Company Registration No. 53103119E

## THIRD PARTY CLAIM

To : Quek Soo Meng  
c/o : Block 3007 #01-404  
Ubi Road 1  
Singapore 408701

Date : 6th September 2021

Our Ref : PA/MI/21/1017/1

### REFERENCE :

ASSIGNED BY : Owner  
ASSIGNED ON : 20th August 2021  
WORKSHOP : Huat Automobile Air Con Service  
Block 3007 #01-404  
Ubi Road 1  
Singapore 408701  
ACCIDENT DATE : 18th August 2021  
SURVEY DATE : 20th August 2021

*Handwritten:*  
2/5 & 12.500  
10 kg

### VEHICLE DETAILS :

REGN PLATE	: SJK 6462 J	COLOUR	: Black
MAKE & MODEL	: Toyota Altis 1.6	GEN BODY WORK	: Good
YEAR REGN	: 2008	AUDIO PLAYER	: Yes
ENG CAPACITY	: 1598cc	AIR CONDITIONER	: Yes
ENGINE NO.	: 3ZZ4804582	STEERING	: Serviceable
CHASSIS NO	: MR053ZEE106121425	HAND BRAKE	: Serviceable
MILEAGE	: 272734Km	FOOT BRAKE	: Serviceable

### TYRES SIZE & CONDITION :

FRONT O/S : Pirelli 205/55 R 16 approximately 60%  
FRONT N/S : Pirelli 205/55 R 16 approximately 60%  
REAR O/S : Pirelli 205/55 R 16 approximately 60%  
REAR N/S : Pirelli 205/55 R 16 approximately 60%

Note : The above percentage represent the remaining estimated life of the tyre treads.

**GENERAL DESCRIPTION OF DAMAGES :**

At the time of inspection, we noted that this vehicle sustained damages along the o/s body length.  
For more details of the damages, please see schedule and photographs attached.

Attached one hundred & fifteen (115) photographs taken during our inspections.

**CONCLUSIONS & RECOMMENDATIONS :**

ORIGINAL QUOTATION : \$ 19,407.73

REVISED QUOTATION : \$ 13,900.00 (Lump Sum)

We have thoroughly inspected each and every item on the estimate against the physical damages found on the vehicle. We have listed the breakdown of our findings and our recommendations as per assessment attached.

In normal circumstances, the repairs would take approximately ten (10) days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** repair to the vehicle and the survey was conducted strictly on a '**WITHOUT PREJUDICE**' basis. We hope that this report will be of assistance to you in dealing with this matter.

Should you discover any discrepancy in this report, please kindly notify us within two (2) weeks or this report will be treated as valid.

The information contained in these documents is privileged and confidential and is for the exclusive use of the addressee's designation. If you are not the addressee, any enclosure, reproduction, distributions or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for its return.

# PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s Huat Automobile Air Con Service  
Block 3007 #01-404  
Ubi Road 1  
Singapore 408701

Our Ref: PA/MI/21/1017/1

Veh. No.: SJK 6462 J

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

## LIST PARTS

1 pc	Front o/s fender	645.10 body rd	dented	\$ 642.10	\$ 642.10 ✓
1 pc	Front o/s fender 'VVTI' emblem	neu	necessary	\$ 65.20	\$ 65.20 ✓
1 pc	Front o/s fender inner shield	for	distorted	\$ 166.10	\$ 166.10 ✓
1 pc	Front o/s fender inner panel	R	repairable	\$ 455.80	\$ - X
1 pc	Front o/s door	12260 body rd	dented	\$ 1,271.50	\$ 1,271.50 ✓
1 pc	o/s door outer mirror assy	320	holder snapped	\$ 844.90	\$ 844.90 ✓
1 pc	Front o/s door outer protector	2.5	dented/ bent	\$ 311.50	\$ 311.50 ✓
1 pc	Front o/s door inner lock	623.20 Jm	dented/ jammed	\$ 603.20	\$ 603.20 ✓
1 pc	Front o/s door glass outer moulding	321	dented/ bent	\$ 141.80	\$ 141.80 ✓
1 pc	Front o/s door inner rubber	neu	necessary	\$ 168.20	\$ 168.20 ✓
1 pc	Front o/s door inner trim board	2224	holder snapped	\$ 925.40	\$ 925.40 ✓
1 pc	Front o/s door glass regulator & motor	2211/2m	dented/ failed	\$ 415.90	\$ 415.90 ✓
1 pc	Front o/s door outer handle	221	bent	\$ 245.10	\$ 245.10 ✓
1 pc	Front o/s door outer handle knock	221	dented	\$ 30.00	\$ 30.00 ✓
1 pc	Front o/s door checker	221	bent	\$ 121.00	\$ 121.00 ✓
2 pcs	Front o/s door hinge @\$94.00	221	bent	\$ 188.00	\$ 188.00 ✓
1 set	Front o/s door black sticker	neu	necessary	\$ 60.00	\$ 60.00 ✓
1 pc	Rear o/s door	1268.10	dented	\$ 1,260.10	\$ 1,260.10 ✓
1 pc	Rear o/s door outer protector	2.5	dented	\$ 299.10	\$ 299.10 ✓
1 pc	Rear o/s door inner lock	Jm	dented/ jammed	\$ 560.80	\$ 560.80 ✓
1 pc	Rear o/s door inner trim board	221.40	holder snapped	\$ 745.10	\$ 745.10 ✓
1 pc	Rear o/s door inner rubber	neu	necessary	\$ 145.10	\$ 145.10 ✓
1 pc	Rear o/s door glass outer moulding	221	bent	\$ 132.50	\$ 132.50 ✓
1 pc	Rear o/s door glass regulator & motor	221/2m	dented/ bent	\$ 388.00	\$ 388.00 ✓
1 pc	Rear o/s door outer handle	221	serviceable	\$ 245.10	\$ - X
1 set	Rear o/s door black sticker	neu	necessary	\$ 60.00	\$ 60.00 ✓
list parts c/f				\$ 10,491.50	\$ 9,790.60

# PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s Huat Automobile Air Con Service  
Block 3007 #01-404  
Ubi Road 1  
Singapore 408701

Our Ref: PA/MI/21/1017/1

Veh. No.: SJK 6462 J

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

list parts b/f

\$ 10,491.50 \$ 9,790.60

1 pc	O/s centre pillar	dented R	\$ 688.10	\$ 688.10 X
1 pc	Rear o/s fender	dented 40/50	\$ 1,160.10	\$ 1,160.10 ✓
1 pc	Rear o/s fender inner trim	serviceable 9/10	\$ 244.80	\$ - X
1 pc	Rear bumper	deformed 0.5	\$ 561.50	\$ 561.50 ✓
1 pc	Rear bumper lower skirting	deformed R	\$ 680.00	\$ 680.00 X
1 pc	O/s taillamp	cracked CR	\$ 380.10	\$ 380.10 ✓
1 pc	O/s rocker panel	dented 20	\$ 788.20	\$ 788.20 ✓
1 pc	O/s rocker panel outer skirting	cracked 70/10	\$ 650.50	\$ 650.50 ✓
1 pc	O/s rocker panel inner garnish	distorted 20/10	\$ 645.50	\$ 645.50 ✓
			\$ 16,290.30	\$ 15,344.60
Less 25%			\$ 4,072.58	\$ 3,836.15
			\$ 12,217.73	\$ 11,508.45

## S/NETT PARTS

1 set	Front o/s fender inner shield clip	necessary 100	\$ 50.00	\$ 50.00 ✓
1 set	Front o/s door inner trim board clip	necessary 100	\$ 50.00	\$ 50.00 ✓
1 set	Rear o/s door inner trim board clip	necessary 100	\$ 50.00	\$ 50.00 ✓
1 pc	Rear windscreen glass sealant	necessary 100	\$ 50.00	\$ 50.00 40
1 pc	Rear windscreen inner seal	necessary 100	\$ 50.00	\$ 50.00 60
1 set	Rear bumper clip	necessary 100	\$ 50.00	\$ 50.00 ✓
1 pc	Front o/s sport rim	dented 100	\$ 800.00	\$ 500.00 ✓
1 pc	Rear o/s sport rim	dented	\$ 800.00	\$ 500.00 X
1 set	O/s door visor	necessary 100	\$ 100.00	\$ 100.00 ✓
			\$ 2,000.00	\$ 1,400.00

## PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s Huat Automobile Air Con Service  
Block 3007 #01-404  
Ubi Road 1  
Singapore 408701

Our Ref : PA/MI/21/1017/1

Veh. No. : SJK 6462 J

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

### LABOUR CHARGES

To disconnect and check electrical wiring,  
harness, wire sockets, etc.

To remove and reinstall damaged parts, test  
and rectify for proper functioning.

\$ 50.00 \$ 30.00 ✓

To check and re-adjust computerised wheel  
alignment.

\$ 150.00 \$ 100.00 ✓

To remove and replace front and rear o/s  
sport rims and carry out wheel balancing.

\$ 80.00 \$ 50.00 ✓

To remove and replace front and rear o/s  
door panels including transfer of fittings and  
mechanism.

\$ 180.00 \$ 150.00 ✓

To remove and refix inner trims, garnishes,  
linings and upholstery to facilitate repairs.

\$ 150.00 \$ 100.00 ✓

To remove and refix rear windscreen glass  
to facilitate repairs and perform water test.

\$ 150.00 \$ 120.00 ✓

To mount vehicle onto chassis alignment  
bench and to reset chassis alignment to  
recommended specification.

\$ 380.00 \$ 380.00 ✗

To apply rustproofing, reseal tuff-coating  
treatment to replaced/ repaired parts and  
panels.

\$ 150.00 \$ 150.00 ✓

# PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s Huat Automobile Air Con Service  
Block 3007 #01-404  
Ubi Road 1  
Singapore 408701

Our Ref: PA/MI/21/1017/1

Veh. No.: SJK 6462 J

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

## LABOUR CHARGES

To remove and refix fuel tank to facilitate repairs.

\$ 100.00 \$ <sup>u7</sup> - X


To remove and replace damaged parts as listed above including reinstatement of the necessary attachments and fittings to facilitate repairs. Jack up, straighten, panel beat and reshape the affected parts and components. To correct and realign the necessary parts.

\$ 1,800.00 \$ 1,600.00 ✓

To putty and spray painting on damaged portion including touch up paint on accident affected areas.

\$ 2,000.00 \$ 1,800.00 ✓  
\$ 19,407.73 \$ 17,388.45

The repairer has agreed to undertake repairs on a contractual basis at **Lump Sum \$ 13,900.00** corresponding to supply of parts, labour and spray painting charges.

  
**CHUAH POH SIONG GARY**  
**CAE, MIMI, AMSOE,**  
**AMIRTE, AMSAE-AUS, MSAAA**

P- 13976.5  
252  
1048237  
1060  
4100  
1056237  
12813