

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21010025/EGA3Q2**Date:** 17/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900097230
Claimant Vehicle No :	SMR912U	Insured Vehicle No :	SLC3299C
Date of Loss:	26/09/2021	Nature of Claim:	TP
		Claim No:	7586156757SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR912U		
Make & Model:	VOLKSWAGEN TOURAN, 1.4 1.4 TSI CL 5T13NZ (A)	Engine No:	CZDA37443
Reg. Date:	18/12/2019 (Man. Year: 2019)	Chassis No:	WVGZZZ1TZKW063134
Colour:	Blue	Odometer:	42307 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,315.36	6,202.04	3,113.32	33.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,630.00	5,450.00	6,180.00	53.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,945.36	11,652.04	9,293.32	44.37
+ GST 7.00/7.00% (S\$)	1,466.18	815.64	650.54	44.37
Nett Amount (S\$)	22,411.54	12,467.68	9,943.86	44.37
+ Car Rental (7.0 x S\$80.00/day + 7.00% GST) (S\$)		599.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		13,068.88		

INSPECTION

Date of Assignment:	30/09/2021		
Date Inspected:	30/09/2021	Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	5.0 days		

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TRUNK LID	Dented	2,382.62 FS	*2,382.62 FS
2	2	*1K WINDOW ADHESIVE	Necessary	102.32 FS	*102.32 FS
3	1	*ALL PURPOSE CLEANER	Necessary	97.37 FS	*97.37 FS
4	1	*PRIMER	Necessary	28.44 FS	*28.44 FS
5	1	*ACTIVATOR FOR PRECOATED W	Necessary	26.15 FS	*26.15 FS
6	2	*APPLICATOR	Necessary	20.88 FS	*20.88 FS
7	1	*PACKING ADHESIVE NUMBER PLATE PACKING	Necessary	30.50 FS	*30.50 FS
8	2	*RIVETTED CAP NUT	Necessary	5.00 FS	*5.00 FS
9	1	*SPOILER SATIN BLACK REAR W/SCREEN SIDE TRIM LH	Necessary	266.78 FS	*266.78 FS
10	1	*SPOILER SATIN BLACK REAR W/SCREEN SIDE TRIM RH	Necessary	279.12 FS	*279.12 FS
11	1	*HOOD LATCH BOOT LID LOCK	Not Necessary	174.72 FS	*- FS
12	1	*PUSHBUTTON FOR ELECTRIC L PUSH BUTTON WITH CAMERA	Not Necessary	1,505.90 FS	*- FS
13	1	*WEBBING ADHESIVE TAPE	Necessary	27.09 FS	*27.09 FS
14	1	*ADDITINAL BRAKE LIGHT WI 3RD BRAKELIGHT	Necessary	228.77 FS	*228.77 FS
15	1	*TAILLIGHT WITH BACK -UP LI LHS TAILLIGHT INNER	Not Necessary	263.29 FS	*- FS
16	1	*TAILLIGHT WITH BACK -UP LI RHS TAILLIGHT INNER	Cut	263.29 FS	*263.29 FS
17	1	*LED LICENCE PLATE LIGHT	Broken	104.26 FS	*104.26 FS
18	1	*COVER FOR BUMPER PRIMED	Dented	1,438.75 FS	*1,438.75 FS
19	1	*SPOILER SATIN BLACK	Crushed	332.69 FS	*332.69 FS
20	4	*RIVET	Necessary	4.72 FS	*4.72 FS
21	1	*BUMPER REINFORCEMENT	Not Necessary	549.77 FS	*- FS
22	1	*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	65.34 FS	*- FS
23	1	*GUIDE PIECE LHS BUMPER BRACKET (UPPER)	Not Necessary	42.45 FS	*- FS
24	1	*GUIDE PIECE RHS BUMPER BRACKET (UPPER)	Not Necessary	42.45 FS	*- FS
25	1	*GUIDE PIECE LHS BUMPER BRACKET (SIDE)	Not Necessary	34.70 FS	*- FS
26	1	*GUIDE PIECE RHS BUMPER BRACKET (SIDE)	Not Necessary	34.70 FS	*- FS
27	1	*REAR NUMBER PLATE	Cut	80.00 FS	*80.00 FS
28	1	*REVERSE SENSOR	Not Necessary	400.00 FS	*- FS
29	1	*NAME PLATE -TOURAN	Necessary	74.51 FS	*74.51 FS
30	1	*VW SIGN BLACK/BRIGHT CHRO	Crushed	108.68 FS	*108.68 FS
31	1	*BOOT LID TRIM COVER	Crushed	300.10 FS	*300.10 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 9,315.36 6,202.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	4,200.00	1,680.00
2	SPRAY PAINT	New	4,000.00	1,600.00
3	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
4	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
5	R&R REAR W/SCREEN	New	840.00	840.00
6	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
7	R&R RR LUGGAGE TRIM TO REPAIR END PANEL	New	840.00	0.00
8	REAR WATER LEAK TEST	New	150.00	150.00
Gross Labour Cost (\$)			11,630.00	5,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >