

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21010026/EGA3Q2**Date:** 10/02/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070119207
Claimant Vehicle No :	YP4059A	Insured Vehicle No :	SMU4731H
Date of Loss:	03/08/2021	Nature of Claim:	TP
		Claim No:	9446674787SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP4059A		
Make & Model:	MERCEDES-BENZ SPRINTER 516CDI, 2.1 D 3665	Engine No:	65195533602054
	HIGH ROOF A/T ABS (A)	Chassis No:	WDB9066532P301360
Reg. Date:	22/09/2016 (Man. Year: 2016)	Odometer:	210239 km
Colour:	Multi-colour		
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75 R16C	Rear Tyre Size:	195/75 R16C
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,341.65	1,317.71	23.94	1.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	350.00	250.00	41.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,941.65	1,667.71	273.94	14.11
+ GST 7.00/7.00% (S\$)	135.92	116.74	19.18	14.11
Nett Amount (S\$)	2,077.57	1,784.45	293.12	14.11
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,086.45		

INSPECTION

Date of Assignment:	27/09/2021	
Date Inspected:	01/10/2021 Inspected At:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23., #01-06 Midview Building Singapore 659578
Estimated Period of Repair:	2.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR STEP PANEL BOARD	Bent	629.29 FL	*629.29 FL
2	1		*REAR STEP PANEL BOARD RIVET	Necessary	23.94 FS	*20.00 FS
3	1		*REAR BUMPER	Broken	590.39 FL	*590.39 FL
4	1		*SET REAR SENSOR	Broken	220.00 FS	*200.00 FS
					Sub Total (\$\$)	1,463.62 1,439.68
					- List Item Discount on L Items 10.00/10.00% (\$\$)	121.97 121.97
					Total Parts (\$\$)	1,341.65 1,317.71

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPAIR ,REPLACE & INSTALL DAMAGED PARTS	New	500.00	300.00
2	TO R&R SENSOR WIRING	New	100.00	50.00
Gross Labour Cost (\$)			600.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >