

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21010029/R1EA3Q2**Date:** 03/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100394374
Claimant Vehicle No :	SHB5318X	Insured Vehicle No :	GBD5460C
Date of Loss:	17/09/2021	Nature of Claim:	TP
		Claim No:	4986516988SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5318X		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS109013
Reg. Date:	30/11/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU803575427
Colour:	Maroon	Odometer:	494051 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 5 mm	Rear Left Side:	Sailun 5 mm
Front Right Side:	Sailun 5 mm	Rear Right Side:	Sailun 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,416.30	132.98	4,283.32	96.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,292.00	680.00	1,612.00	70.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,708.30	812.98	5,895.32	87.88
Approved Total (Overridden) (S\$)		800.00		
Nett Amount (S\$)	6,708.30	800.00	5,908.30	88.07
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$111.82/day) (S\$)		447.28		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		1,454.28		
Global Sum Settlement (S\$)		1,450.00		

INSPECTION

Date of Assignment:	22/09/2021	
Date Inspected:	22/09/2021	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR FRONT COVER OUTER HANDLE ,LH (DISC 25%)	Necessary	17.30 F	*12.98 F
2	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
3	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
4	1		*MIRROR ASSY ,OUTER REAR VIEW ,LH	Not Necessary	1,283.90 F	*- F
5	1		*DOOR OUTER HANDLE FRONT LH	Not Necessary	378.90 F	*- F
6	1		*WEATHERSTRIP ,REAR DOOR NO.2 LH	Not Necessary	33.20 F	*- F
7	1		*COVER ,OUTER MIRROR ,LH	Repair	89.50 F	*- F
8	1		*PANEL SUB-ASSY ,FRONT DOOR LH	Repair	1,249.60 F	*- F
9	1		*PANEL SUB-ASSY ,REAR DOOR ,LH	Repair	1,243.90 F	*- F
Total Parts (\$\$)						4,416.30 132.98

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	200.00
2	SPRAY PAINT	New	936.00	480.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
4	TO TRANSFER DOOR MECHANISM	New	240.00	0.00
5	TO REMOVE AND REFIT WIRE HARDESS	New	200.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
7	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			2,292.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >