

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21010031/GUF3N2**Date:** 18/10/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ000349
Claimant Vehicle No :	SH7335X	Insured Vehicle No :	SMX7191E
Date of Loss:	27/09/2021	Nature of Claim:	TP
		Claim No:	M2104493

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7335X		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU713750
Reg. Date:	13/12/2017 (Man. Year: 2016)	Chassis No:	KMHLB41UMHU098583
Colour:	Blue	Odometer:	641463 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,442.58	748.64	693.94	48.10
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,190.00	900.00	290.00	24.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,643.58	1,659.64	983.94	37.22
Approved Total (Overridden) (S\$)		1,350.00		
(S\$)	2,643.58	1,350.00	1,293.58	48.93
+ GST 7.00/7.00% (S\$)	185.05	94.50	90.55	48.93
Nett Amount (S\$)	2,828.63	1,444.50	1,384.13	48.93

INSPECTION

Date of Assignment:	27/09/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	27/09/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Oct 2021)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH7335X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER COVER	Cracked	553.00 FL	-	*553.00 FL
2	1		*BUMPER BUMPER CLIPS	Necessary	2.20 FL	-	*2.20 FL
3	1		*BUMPER BUMPER BRACKET	Deformed	35.60 FL	-	*35.60 FL
4	1		*BUMPER BUMPER REFLECTOR RH	Cut	32.00 FL	-	*32.00 FL
5	1		*TAIL LAMP RH	Not Necessary	697.80 FL	-	*- FL
6	1		*REAR REVERSE SENSOR	Not Necessary	135.70 FS	-	*- FS
7	1		*REAR BUMPER UNDER COVER	Cut	228.00 FL	-	*228.00 FL
Supplementary #1							
8	1		*BOOT LID MOULDING CHROME	Broken	85.00 FL	-	*85.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,769.30	935.80
- List Item Discount on L Items 20.00/20.00% (S\$)	326.72	187.16
Total Parts (S\$)	1,442.58	748.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	450.00	280.00
2	SPRAY PAINTING	New	500.00	500.00
3	CHECK WIRING AND LIGHTING	New	60.00	20.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00	40.00
5	TOFF COATING	New	60.00	0.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
6	TOWING FEE	New	60.00	60.00
Gross Labour Cost (\$\$)			1,190.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >