

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010032/BTCN2**Date:** 08/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00043342100
Claimant Vehicle No :	SFF6113R	Insured Vehicle No :	GBJ4152S
Date of Loss:	23/09/2021	Nature of Claim:	TP
		Claim No:	SNM21D205447/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFF6113R	Engine No:	8ARZ036959
Make & Model:	LEXUS GS200T, 2.0 EXECUTIVE (A)	Chassis No:	JTHBA1BL80A002221
Reg. Date:	16/04/2016 (Man. Year: 2016)	Odometer:	66809 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40ZR19	Rear Tyre Size:	265/35ZR19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,709.70	6,556.24	13,153.46	66.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,940.00	1,340.00	2,600.00	65.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,649.70	7,896.24	15,753.46	66.61
Approved Total (Overridden) (\$\$)		6,300.00		
(\$\$)	23,649.70	6,300.00	17,349.70	73.36
+ GST 7.00/7.00% (\$\$)	1,655.48	441.00	1,214.48	73.36
Nett Amount (\$\$)	25,305.18	6,741.00	18,564.18	73.36

INSPECTION

Date of Assignment:	27/09/2021	
Date Inspected:	28/09/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Oct 2021)
Parts:	143	LEXUS GS200T 2.0 EXECUTIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFF6113R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	1,050.00 FL	*1,050.00 FL
2	1		*REAR BUMPER LOWER	Broken	430.00 FL	*250.00 FL
3	1		*REAR BUMPER LOWER TOWING COVER	Not Damaged	25.00 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER R	Necessary	99.00 FL	*99.00 FL
5	1		*REAR BUMPER SIDE RETAINER L	Necessary	99.00 FL	*99.00 FL
6	1		*REAR BUMPER SPONGE	Broken	299.00 FL	*155.00 FL
7	1		*REAR BUMPER REINFORCEMENT	Not Damaged	894.00 FL	*- FL
8	1		*REAR BUMPER SUPPORT BRACKET R	Broken	154.00 FL	*85.80 FL
9	1		*REAR BUMPER SUPPORT BRACKET L	Broken	154.00 FL	*85.80 FL
10	1		*REAR BUMPER REFLECTOR R	Not Damaged	70.00 FL	*- FL
11	1		*REAR BUMPER REFLECTOR L	Not Damaged	70.00 FL	*- FL
12	1		*REAR BUMPER TOWING COVER	Repeated	30.00 FL	*- FL
13	1		*REAR BUMPER SENSOR (4 Pcs)	Short Circuit (2 Pcs only)	1,250.00 FL	*530.00 FL
14	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Damaged	489.00 FL	*- FL
15	1		*REAR BUMPER BLIND SPOT RADAR SENSOR R	Not Damaged	1,359.00 FL	*- FL
16	1		*REAR BUMPER BLIND SPOT RADAR SENSOR L	Not Damaged	1,359.00 FL	*- FL
17	1		*BOOTLID	Bent	895.00 FL	*780.00 FL
18	1		*BOOTLID OUTER GARNISH	Not Damaged	280.00 FL	*- FL
19	1		*BOOTLID INSULATOR	Not Damaged	1,250.00 FL	*- FL
20	1		*BOOTLID OUTER GARNISH CHROME MOULDING	Repeated	80.00 FL	*- FL
21	1		*BOOTLID HINGE R	Not Damaged	180.00 FL	*- FL
22	1		*BOOTLID HINGE L	Not Damaged	180.00 FL	*- FL
23	1		*BOOTLID LAMP R	Not Damaged	690.00 FL	*- FL
24	1		*BOOTLID LAMP L	Not Damaged	690.00 FL	*- FL
25	1		*BOOTLID TOP LOCK	Jammed	490.00 FL	*490.00 FL
26	1		*BOOTLID LOWER LOCK	Not Damaged	65.00 FL	*- FL
27	1		*BOOTLID WEATHERSTRIP	Not Damaged	235.00 FL	*- FL
28	1		*BOOTLID EMBLEM	Necessary	63.00 FL	*63.00 FL
29	1		*BOOTLID EMBLEM LEXUS	Necessary	80.00 FL	*80.00 FL
30	1		*BOOTLID EMBLEM GS	Necessary	78.00 FL	*78.00 FL
31	1		*BOOTLID EMBLEM 250	Necessary	78.00 FL	*78.00 FL
32	1		*BOOTLID STOPPER	Not Necessary	80.00 FL	*- FL
33	1		*TAILLAMP R	Broken	1,150.00 FL	*1,150.00 FL
34	1		*TAILLAMP L	Broken	1,150.00 FL	*1,150.00 FL
35	1		*TAILLAMP SIDE GARNISH R	Not Necessary	120.00 FL	*- FL
36	1		*TAILLAMP SIDE GARNISH L	Not Necessary	120.00 FL	*- FL
37	1		*TAILLAMP LOWER BRACKET R	Broken	85.00 FL	*85.00 FL
38	1		*TAILLAMP LOWER BRACKET L	Broken	85.00 FL	*85.00 FL
39	1		*REAR FENDER INNER TRIM R	Not Damaged	730.00 FL	*- FL
40	1		*REAR FENDER INNER TRIM L	Not Damaged	630.00 FL	*- FL
41	1		*REAR END PANEL	Dented	780.00 FL	*780.00 FL
42	1		*REAR END PANEL INNER	Not Damaged	184.00 FL	*- FL
43	1		*REAR END PANEL TOP GARNISH	Not Damaged	398.00 FL	*- FL
44	1		*REAR EXHAUST INSULATOR	Not Damaged	360.00 FL	*- FL
45	1		*REAR EXHAUST PIPE	Not Damaged	2,180.00 FL	*- FL

Report was unsubmitted during this print-out.

10/8/21, 2:32 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	2		*REAR EXHAUST MOUNTING	Not Necessary	116.00 FL	*- FL
47	1		*REAR NUMBER PLATE	Not Damaged	50.00 FS	*- FS
48	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
49	1		*BOOTLID SEALANT	Not Necessary	100.00 FS	*- FS
50	1		*SET BOOTLID INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
51	1		*SET TAILLAMP CLIPS	Necessary	60.00 FS	*40.00 FS
52	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*30.00 FS
53	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					21,843.00	7,273.60
- List Item Discount on L Items 10.00/10.00% (S\$)					2,133.30	717.36
Total Parts (S\$)					19,709.70	6,556.24
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT,REMOVE & REFIX PARTS	New	1,500.00	600.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,200.00	600.00
3	TO REMOVE & REFIX REAR UPHOLSTERY	New	150.00	0.00
4	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	60.00
5	TO REMOVE & REFIX REAR EXHAUST PIPE TO FACILITATE REPAIRS	New	150.00	0.00
6	TO REMOVE & REFIX REAR BOOTLID MECHANISM	New	120.00	80.00
7	TO TUFF COAT	New	150.00	0.00
8	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
9	WIRING & BULB CHECK	New	100.00	0.00
10	TO CALIBRATE SYSTEM	New	350.00	0.00
Gross Labour Cost (\$\$)			3,940.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >