



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 6277A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED / CUT	856.00	856.00
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	120.20	-
1	REAR BUMPER BRACKET	NOT NECESSARY	68.20	-
1	REAR BUMPER SIDE GARNISH	NOT NECESSARY	169.00	-
1	REAR BUMPER REFLECTOR	NOT NECESSARY	145.00	-
1	REAR RIGHT SIDE TAILLAMP	NOT NECESSARY	680.40	-
1	REAR RIGHT SIDE FENDER (NPA)	NOT NECESSARY	-	-
1	REAR RIGHT SIDE FENDER INNER TRIM GARNISH	NOT NECESSARY	463.20	-
	LESS 20% DISCOUNT		-500.40	-171.20
			2,001.60	684.80
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)	NOT NECESSARY	80.00	-
1	REVERSE SENSOR C/W MODULE (SN)	NOT NECESSARY	300.00	-
			380.00	-
	<u>LABOUR</u>			
	TO REMOVE, REPLACE DAMAGED LAMPS & CHECK UP WIRING.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIT INNER GARNISHES TO ASSIST REPAIR.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT REAR REVERSE SENSOR.	NOT NECESSARY	150.00	-
	TO APPLY UNDERCOATING.	NOT NECESSARY	200.00	-
	PANEL BEATING.		700.00	150.00
	TO RE-SPRAY THE AFFECTED AREAS.		800.00	200.00
			2,080.00	350.00
	GRAND TOTAL		4,461.60	1,034.80



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			800.00
---	--	--	--------

Report Ref No. CS/UOI21010042/Uqf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.