

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE I	PTE LTD	R	Ref:	CS3/ASM21010044/Euce2
	8 SHENTON WAY AXA TOWERSING		D	Date:	30/09/2021
	ATTN: CHAN KIAN	CHUAN	С	ode:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 7088B	Veh. Inspected		FBK 2391B
	Policy No.		Coverage (\$)		0.00
	Claim No.	S1M03HUE	Excess (\$)		0.00
	Assign From	CHAN KIAN CHUAN	Assign Date		28/09/2021
2. Vehicle Particulars & Condition					
	Make & Model	K.T.M. RC390	c.c		373
	Engine No.	HIDDEN	Year of Reg.		2015
	Chassis No.	VBKJYJ407FC206080	Colour		ORANGE
	Odometer	44593 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	120/60-17	PIRELLI		4 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	160/60-17	PIRELLI		4 mm
	L/H Rear Tyre				mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
5.	General Information				
	Accident Date	13/09/2021	Inspect Date / Ti	me	28/09/2021 (12:23 PM)
	Survey held at	JL POWERSPORTS			
	1 SOON LEE STREET #05-53 PIONEER CENTRE SINGAPORE 627605				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM21010044/Euce2

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser