

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21010047/EES3Q2**Date:** 17/01/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMM3994P	Insured Vehicle No :	SML5521M
Date of Loss:	18/09/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004092

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM3994P	Engine No:	CJS304166
Make & Model:	VOLKSWAGEN PASSAT, 2.0 TFSI (A)	Chassis No:	WVWZZZ3CZKE080931
Reg. Date:	27/06/2019 (Man. Year: 2019)	Odometer:	36848 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,687.12	2,000.50	1,686.62	45.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,480.00	2,920.00	3,560.00	54.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,167.12	4,920.50	5,246.62	51.60
+ GST 7.00/7.00% (S\$)	711.70	344.44	367.26	51.60
Nett Amount (S\$)	10,878.82	5,264.94	5,613.88	51.60
+ Car Rental (3.0 x S\$120.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,632.39		

INSPECTION

Date of Assignment:	28/09/2021	
Date Inspected:	29/09/2021	Inspected At: Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2021)
Parts:	143	VOLKSWAGEN PASSAT 2.0 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM3994P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*INSCRIPTION BRIGHT CHROME NAME PLATE -PASSAT	Necessary	75.93 FS	*75.93 FS
2	1		*COVER PRIMED	Dented	1,720.21 FS	*1,720.21 FS
3	1		*SPOILER PRIMED	Not Necessary	295.43 FS	*- FS
4	1		*BUMPER REINFORCEMENT	Not Necessary	661.70 FS	*- FS
5	10		*POP-RIVET	Necessary	12.30 FS	*12.30 FS
6	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	63.45 FS	*- FS
7	1		*GUIDE LHS BUMPER BRACKET (UPPER)	Not Necessary	23.81 FS	*- FS
8	1		*GUIDE RHS BUMPER BRACKET (UPPER)	Not Necessary	23.81 FS	*- FS
9	1		*GUIDE PIECE LHS BUMPER BRACKET (SIDE)	Not Necessary	40.70 FS	*- FS
10	1		*GUIDE PIECE RHS BUMPER BRACKET (SIDE)	Not Necessary	40.70 FS	*- FS
11	1		*SET SENSOR BRACKETS	Necessary	45.72 FS	*45.72 FS
12	1		*2K-PLASTIC ADHESIVE	Necessary	81.16 FS	*81.16 FS
13	1		*BONDING AGENT FOR PLASTIC	Necessary	65.18 FS	*65.18 FS
14	1		*DECORATIVE MOULDING BRIGHT BUMPER CTR LOWER MLDG CHROM	Not Necessary	225.19 FS	*- FS
15	1		*DECORATIVE MOULDING BRIGHT LHS BUMPER LOWER MLDG CHROM	Not Necessary	172.87 FS	*- FS
16	1		*REFLECTOR LHS REFLECTOR OUTER	Not Necessary	69.48 FS	*- FS
17	1		*REFLECTOR LHS REFLECTOR INNER	Not Necessary	69.48 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **3,687.12** **2,000.50**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECJ SHORT CIRCUIT/HARNESS REPAIR	New	280.00	0.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	2,520.00	840.00
4	SPRAY PAINT	New	3,200.00	1,600.00
Gross Labour Cost (\$\$)			6,480.00	2,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >