

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21010051/R1TF3E2

**Date:** 04/10/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800043480
<b>Claimant Vehicle No :</b>	SJP1003H	<b>Insured Vehicle No :</b>	GX1411G
Date of Loss:	19/09/2021	Nature of Claim:	TP
		Claim No:	1312545519SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJP1003H</b>	Engine No:	1ZZ3225936
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDER12WX03002243
Reg. Date:	11/03/2009 (Man. Year: 2009)	Odometer:	129853 km
Colour:	Grey		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	28/09/2021	8 Paragon Pte Ltd (HQ)
Date Inspected:	30/09/2021 Inspected At:	71 WOODLANDS AVE 10 #01-10 WOODLANDS INDUSTRIAL XCHANGE
Estimated Period of Repair:	5.0 days	Singapore 737743

**Adjuster:** MOHD RASUL

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$21,000.00 (EST)

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*TAILGATE	Bent	0.00 F	*- F
4	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
5	1		*TAILGATE MOULDING	Necessary	0.00 F	*- F
6	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
7	1		*TAILGATE RUBBER	Necessary	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
-----------------------------------------------

< END OF ESTIMATES >