

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Affiliated to Federation Internationale Des Experts En Automobile					
	AIG ASIA PACIFIC	INSURANCE PTE LTD	Ref:	CS3/AIG21006449/Vvf3e2-1	
	78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120		Date:	26/10/2021	
	ATTN: SALIHA SY	ED YUSOF	Code	AIG	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBJ 1899R	Veh. Inspected	SJT 6478S	
	Policy No.	1900012257	Coverage (\$)	0.00	
	Claim No.	1550589506SG	Excess (\$)	0.00	
	Assign From	SALIHA SYED YUSOF	Assign Date	28/09/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI AVANTE 1.6 A	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	KMHDU41BR9U771057	Colour	SILVER	
	Odometer	214954 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/60 R15	FIRENZA	5 mm	
	L/H Front Tyre	195/60 R15	FIRENZA	5 mm	
	R/H Rear Tyre	195/60 R15	FIRENZA	5 mm	
	L/H Rear Tyre	195/60 R15	FIRENZA	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.		General Information			
	Accident Date	05/06/2021	Inspection Date	08/06/2021	
	Survey held at	GARAGE 13 PTE LTD			
	8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				