

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : SNM21D205328/C01/LEWLC Date: 20th Oct 2021

Our Ref : CS/CTI21010054/Ktce2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00 Springleaf Tower Singapore 079909 (The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GBE 5953S ACCIDENT ON 17/09/2021

Instruction was received to inspect the vehicle Reg. No. GBE 5953S. The inspection was conducted on 28/09/2021 at the premises of M/s S & H Motor Pte Ltd, 160 Sin Ming Drive #07-02, Sin Ming Autocity, Singapore 575722.

The following vehicle information was recorded:

Registration Number : GBE 5953S

Make/Model : Mitsubishi Canter FEA01BR2SDEB (CBU)

Year of Registration : 2016 Body Colour : White

Chassis Number : FEA01BA10182

Engine Capacity : 2998 cc Speedometer Reading : 147892 km

The vehicle sustained damages at the front portion. The undercarriage and body structure affected due to collision. The Estimated repair cost of such vehicle is S\$62,345.70 (Sin Dollars: Sixty-Two Thousand Three Hundred Forty-Five and Seventy Cents only.) (Include check items S\$34,240.00Nett) (Details see photographs enclosed)

49,000.00

20,020.00)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "Total Loss".

(a)	If the vehicle to be "Total Loss" Market Value	
	Market value	S\$
	Less: LTA Reimbursement Value (RV)	(S\$

S\$ 28,980.00 Less: Excess (S\$ 350.00)

Nett Liability S\$ 28,630.00

(b) If the vehicle to be "Repair"

Repair Cost (Est) S\$ 62,345.70 (Include check items S\$34,240.00Nett)

Less:Excess (S\$ 350.00)

Nett Liability

S\$ 61,995.70

(a) - (b) = (S\$ 33,365.70)

The amount of estimated saving of S\$33,365.70 if the vehicle to be written off as "Total Loss" instead of to be repair.

Vehicle Inspected By:

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK), MASME(USA), B Bus(Aust),MBA(UK), IEng(UK), MIIE(mech), MinstAEA, MFIEA, MIRTE,MIMI,MSAE,MCIArd, AM,NIJAAR(USA),

AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.