

|   |        |      |             |
|---|--------|------|-------------|
| 1 | of 2 ? | 100% | Find   Next |
|---|--------|------|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|  |   |                           |                |  |
|--|---|---------------------------|----------------|--|
| <b>Affiliated to Federation Internationale Des Experts En Automobile</b>   |   |                           |                |  |
| EQ INSURANCE COMPANY LTD   |   | Ref: CS3/EQI21010055/Gvf3 |                |  |
| 5 MAXWELL ROAD   |   | Date: 28/09/2021          |                |  |
| #17-00 TOWER BLOCK   |   |                           |                |  |
| MND COMPLEXSINGAPORE 069110  |   | Code: EQI                 |                |  |
| <b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>  |   |                           |                |  |
| <b>Insured Veh.</b>  | GBH 4778Y   | <b>Veh. Inspected</b>     | SFK 9559S      |  |
| <b>Policy No.</b>  |   | <b>Coverage (\$)</b>      | 0.00           |  |
| <b>Claim No.</b>   | DM21HO01429/JT  | <b>Excess (\$)</b>        | 0.00           |  |
| <b>Assign From</b>   | JAIME TAY   | <b>Assign Date</b>        | 28/09/2021     |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                           |                |  |
| <b>Make &amp; Model</b>  | c.c   |                           | 0              |  |
| <b>Engine No.</b>  | HIDDEN  | <b>Year of Reg.</b>       |                |  |
| <b>Chassis No.</b>   |   | <b>Colour</b>             |                |  |
| <b>Odometer</b>  | -   | <b>Steering</b>           |                |  |
| <b>Brakes</b>  |   | <b>Modification</b>       |                |  |
| <b>General</b>   |   |                           |                |  |
| <b>3. Conditions of Tyres</b>  |   |                           |                |  |
|  | <b>Size</b>   | <b>Make</b>               | <b>Balance</b> |  |
| <b>R/H Front Tyre</b>  |   |                           | mm             |  |
| <b>L/H Front Tyre</b>  |   |                           | mm             |  |
| <b>R/H Rear Tyre</b>   |   |                           | mm             |  |
| <b>L/H Rear Tyre</b>   |   |                           | mm             |  |
| <b>4. Description of Damages</b>   |   |                           |                |  |
|  |   |                           |                |  |
| <b>5. General Information</b>  |   |                           |                |  |
| <b>Accident Date</b>   | 25/09/2021  | <b>Inspection Date</b>    | 29/09/2021     |  |
| <b>Survey held at</b>  | Y S AUTOMOBILE SERVICE<br>BLK 5 DEFU LANE 10<br>#01-580 DEFU LANE INDUSTRIAL PARK 3<br>SINGAPORE 539186 |                           |                |  |
| <b>5a. Remarks</b>   |   |                           |                |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |   |                           |                |  |